

**Recall Quarterly Report****15V-859****Manufacturer Name :** Daimler Trucks North America LLC**NHTSA Recall No. / MFR Recall No. :** 15V-859 /FL-699**Recall Subject :** Front Driveshaft may Disconnect**Owner Notification Beginning Date :** FEB 02, 2016**Owner Notification End Date:** FEB 02, 2016

Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
4	JAN 30, 2017	2016-4	43	24	0	0
3	OCT 28, 2016	2016-3	43	23	0	0
2	JUL 30, 2016	2016-2	43	21	0	0
1	MAY 02, 2016	2016-1	43	17	0	0

This Document Last Updated : JAN 31, 2017

**Definitions :**

**Report Quarter :** The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012).

**Recall Population :** The total number of products recalled by the manufacturer.

**Total Remedied :** The total number of products either remedied, inspected without needing remedy, or returned to inventory.

**Total Unreachable :** Products deemed unreachable as owner notifications were unable to be delivered.

**Total Removed :** Products that have been scrapped, stolen, or exported.