

Part 573 Safety Recall Report**15V-008****Manufacturer Name :** Winnebago Industries, Inc**Submission Date :** JAN 12,2015**NHTSA Recall No. :** 15V-008**Manufacturer Recall No. :** P62**Manufacturer Information :**

Manufacturer Name : Winnebago Industries, Inc

Address : PO BOX 152

605 W. Crystal Lake Rd. Forest City IA 50436

Company phone : 1-641-585-3535

Population :

Number of potentially involved : 1,107

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2015 Winnebago and Itasca Travato, Trend and Viva

Vehicle Type : LIGHT VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : The motor vehicles potentially containing the defect are on certain 2014 and 2105 model year Winnebago Travato, 2014 and 2015 Winnebago Trend and 2014 and 2015 Itasca Viva motorhomes built on the Ram ProMaster chassis. The units were built between November 13, 2014 and December 23, 2015. The vehicles are being identified by using the model number and production records showing VIN's.

Production Dates : NOV 13, 2014 - DEC 23, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : In the affected vehicles, the Tire Pressure Monitoring System (TPMS) may fail to learn the locations of the individual sensors while the vehicle is being driven. As a result, the low tire pressure warning light will illuminate, despite the tire pressures being within specification. Should one of those tires loose air pressure, the driver would not be notified of the change in air pressure. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard No. 138, "Tire Pressure Monitoring Systems".

Description of the Safety Risk : If the TPMS light illuminates because the sensors cannot be located, it could mask an actual low tire pressure condition, possibly resulting in tire failure, increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Chrysler Group LLC

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MICHIGAN 48326-2757

Country : United States

Chronology :

Winnebago Industries discovered the defect as a result of a notice from Chrysler Group LLC on January 5, 2015.

Description of Remedy :

Description of Remedy Program : Winnebago Industries has provided Chrysler a current list of owners and will continue to assist them to correct the situation. Chrysler will notify owners, and dealers will update the TPMS module with new software, free of charge.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported