

**Part 573 Safety Recall Report****15V-030****Manufacturer Name :** Highland Ridge RV**Submission Date :** MAY 03, 2016**NHTSA Recall No. :** 15V-030**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Highland Ridge RV

Address : 955 Tuscany Drive

Shipshewana IN 46565

Company phone : 260-768-7771

**Population :**

Number of potentially involved : 284

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2015-2015 Highland Ridge 3x

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Carefree of Colorado Recall 14E078

Model 153x349rls vin 017329 thru 018393 non sequential

Model 153x378rls vin 017350 thru 018043 non sequential

Model 153x379rls vin 017360 thru 018542 non sequential

Model 153x386flr vin 017577 thru 018584 non sequential

Model 153x388rks vin 017341 thru 018559 non sequential

Model 153x397fbs vin 017342 thru 018579 non sequential

Model 153x427bhs vin017343 thru 018563 non sequential

Production Dates : AUG 05, 2014 - NOV 17, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Latitude Awnings may have a mounting screws that attach the lateral arm brackets to the mounting brackets that may not meet specs.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the screw heads break off there is a potential for the lateral support arm to fall in a downward motion ths causing a safety risk.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Carefree of Colorado

Address : 2145 W. 6th Ave  
Broomfield 80020

Country : NR

**Chronology :**

12-17-15 Highland received notice of Carefree recall 14E078 - regarding Latitude awnings manufactured between April 10 and Nov 4, 2014. Highland created scope of units manufactured with the specific awning and within the time frame set by Carefree and submitted the scope with current owner contact information to Carefree 1-06-15.

**Description of Remedy :**

Description of Remedy Program : Carefree will locate and coordinate the replacement of the screws on the Highland Ridge RV units that have the Latitude Awnings. Carefree will notify all Highland Ridge Rv dealers and retail owners directly in writing of the potential problem and the corrective action. Carefree will arrange for re [pairs and labor payment, will create written instructions detailing the correct replacement procedure, and coordinate the shipment of repair parts and labor payment directly to the dealer. Tyhey will also communicate and traqck the progress to Highland Ridge Rv quarterly.

How Remedy Component Differs from Recalled Component : the remedy component meets the required specs to provide the strength to hold the lateral arem of the awning support in place. the recalled component does not meet spec and is thereby suspect.

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported