

**Part 573 Safety Recall Report****15V-039****Manufacturer Name :** Jaguar Land Rover North America, LLC**Submission Date :** JAN 26,2015**NHTSA Recall No. :** 15V-039**Manufacturer Recall No. :** P054**Manufacturer Information :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Address : 555 MACARTHUR BOLULEVARD

MAHWAH NJ 07430

Company phone : 201-760-8534

**Population :**

Number of potentially involved : 74,648

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2006-2012 Land Rover Range Rover

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : 2006-2012 Land Rover Range Rover

Production Dates : APR 15, 2005 - SEP 04, 2012

**VIN (Vehicle Identification Number) Range**

Begin : SALME15466A198146

End : SALMF1E44CA393638

 Not sequential VINs**Description of Defect :**

Description of the Defect : A concern has been identified with brake hoses installed on 2006 to 2012 Model Year (MY) Range Rover vehicles. Customers may experience a loss of brake fluid as a result of rupturing of one or both of the front brake jump (flexi) hoses. This may result in the loss of the front brake circuit. The vehicle braking system is a dual circuit system, one system operates the front braking circuit and the other system operates the rear braking circuit.

A vehicle exhibiting sudden loss of brake fluid will illuminate a red warning triangle on the instrument cluster whilst displaying the words 'check brake fluid'. The driver should seek qualified assistance. Loss of fluid will also result in failure of the front braking circuit. Braking capability will be retained by the rear brake circuit, pedal feel will be degraded and pedal travel extended. Stopping distances will increase.

Description of the Safety Risk : Loss of one of the hydraulic service braking system circuits could compromise vehicle braking and significantly increase the risk of a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Caparo AP Braking

Address : Brake House

Tachbrook Road Leamington Spa FOREIGN STATES CV31 3SF

Country : United Kingdom

**Chronology :**

See Attached "P054 Chronology".

**Description of Remedy :**

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to a Land Rover dealer who will replace both Left Hand and Right Hand front brake hoses.

There will be no charge to owners for this repair.

Customers who have paid for a repair of this defect will be reimbursed by the Jaguar Land Rover reimbursement plan, subject to terms and conditions.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : Mailing of owner notification letters will occur on or before March 13, 2015.  
Notifications to dealers will occur on January 29, 2015.

Planned Dealer Notification Date : JAN 29, 2015 - JAN 29, 2015

Planned Owner Notification Date : MAR 13, 2015 - MAR 13, 2015

\* NR - Not Reported