

**Part 573 Safety Recall Report****15V-062****Manufacturer Name :** Newmar Corporation**Submission Date :** FEB 03,2015**NHTSA Recall No. :** 15V-062**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

**Population :**

Number of potentially involved : 30

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2015-2015 Newmar Essex

Vehicle Type :

Body Style : OTHER

Power Train : DIESEL

**Descriptive Information :** On 2015 Newmar Essex Class A motorhomes, the steering column may have inadequate spline engagement at the steering gear. This could lead to wear and potentially result in the steering shaft becoming disconnected or slipping, causing a loss of steering control and increase the risk of a crash causing injury and/or damage to property.

Production Dates : MAR 13, 2014 - NOV 13, 2014

**VIN (Vehicle Identification Number) Range**

Begin : 4VZVV1E92FC078029

End : 4VZVU1E97FC079583

 Not sequential VINs**Description of Defect :**

**Description of the Defect :** On 2015 Newmar Essex Class A motorhomes, the steering column may have inadequate spline engagement at the steering gear. This could lead to wear and potentially result in the steering shaft becoming disconnected or slipping, causing a loss of steering control and increase the risk of a crash causing injury and/or damage to property.

**Description of the Safety Risk :** If there is inadequate spline engagement at the steering gear, this could lead to wear and potentially result in the steering shaft

**Description of the Cause :** The steering slip shaft, between the steering column and steering gear, may have less than specified engagement of the slip shaft. This may cause premature wear of the slip shaft.

**Identification of Any Warning that can Occur :** NR

**Supplier Identification :**

**Component Manufacturer**

Name : Spartan Motors Inc.

Address : 1541 Reynolds Road  
Charlotte MICHIGAN 48813

Country : United States

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : Spartan will notify owners, dealers will replace the affected slip shaft, free of charge

How Remedy Component Differs from Recalled Component : The new slip shafts will have the minimum specified engagement.

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported