

Part 573 Safety Recall Report**15V-103****Manufacturer Name :** Cruiser RV**Submission Date :** FEB 18,2015**NHTSA Recall No. :** 15V-103**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Cruiser RV
 Address : 7805 North State Road 9
 PO Box 130 Howe IN 46746
 Company phone : 866-277-5630

Population :

Number of potentially involved : 51
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Cruiser RV – Stryker Toy Cruiser RV – Stryker Toy Hauler

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Cruiser RV – Stryker Toy

Production Dates : JUL 21, 2014 - JAN 09, 2015

VIN (Vehicle Identification Number) Range

Begin : 5RXTG2826G2203268

End : 5RXTG2520G2204002

 Not sequential VINs**Description of Defect :**

Description of the Defect : : The optional slide floor in these units is designed to flip up to allow more storage when the slide is in the travel position.

Description of the Safety Risk : If the consumer were to flip the slide floor up, when the trailer is stationary, they could be exposed to exhaust fumes from the generator as well as fumes from the exterior fueling station.

Description of the Cause : This is a design flaw of the optional slide floor. When designed, the intention was for the customer to be able to better utilize the storage area (garage) when the unit was in travel mode.

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

FOREIGN STATES

Country : NR

Chronology :

Late in January (not sure of exact date), we had an internal compliance audit on this make and model and the questions arose as to whether or not this was a safety factor on this unit. On January 26th, we held a meeting to discuss the potential code violation and potential risk associated with this design. We decided that it would be in our and the customer's best interest to eliminate the issue through a recall.

Description of Remedy :

Description of Remedy Program : Manufacturer will locate and contact each customer (or dealer if unit has not been sold) and ship the necessary parts to them for the remedy. The remedy includes, securing the flip up portion of the slide floor that it will be completely sealed to the outside elements and will no longer have the ability to open. The manufacturer will pay for all parts, shipping, and labor for the remedy.

How Remedy Component Differs from Recalled Component : This remedy will not allow the slide floor to be opened either in transit or in a stationary position, which will not allow any outside elements to potentially enter the storage compartment of the trailer and will no longer potentially expose the consumer to those outside elements.

Identify How/When Recall Condition was Corrected in Production : Upon this discovery, Cruiser RV immediately changed the design and is now installing only a solid, non-opening slide floor on these models with the optional slide out. This recall is inclusive of all of the units that were built with this potential risk.

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : MAR 16, 2015 - MAR 20, 2015

Planned Owner Notification Date : MAR 16, 2015 - MAR 20, 2015

* NR - Not Reported