

Part 573 Safety Recall Report**15V-183****Manufacturer Name :** Motor Coach Industries**Submission Date :** MAR 25,2015**NHTSA Recall No. :** 15V-183**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Motor Coach Industries

Address : 200 East Oakton Street

Des Plaines IL 60018

Company phone : 847-285-2085

Population :

Number of potentially involved : 21

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2007-2010 MCI E4500 and J4500 models

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Certain MCI E4500 and J4500 model coaches equipped with Recaro driver's seats that are the subject of Johnson Controls' recall 15E-008.

Production Dates : NOV 21, 2006 - AUG 27, 2009

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : REFER TO NHTSA Recall No. 15E-008 from Johnson Controls, Inc (Recaro Automotive Seating):

The subject buses incorporate a reverse mounting configuration for the tether bar and the Automatic Lock Retractor. The potential exists for all reverse mounted Automatic Locking Retractors to have an interference between the tether bar and the retractor panel door. This condition can allow the tether bar to push into the retractor panel door and to interfere with the locking mechanism. The result is that the seat belt locking pawl may not appropriately lock and the bus driver may not be properly restrained while driving.

Description of the Safety Risk : REFER TO NHTSA Recall No. 15E-008

Johnson Controls reports that improper restraint can increase the risk of injury in the event of a crash.

Description of the Cause : Not reported by Johnson Controls

Identification of Any Warning that can Occur : None reported by Johnson Controls

Supplier Identification :

Component Manufacturer

Name : Johnson Controls, Inc.

Address : 5757 N. Green Bay Ave.

Milwaukee FOREIGN STATES 53209

Country : NR

Chronology :

MCI received Johnson Controls' notice of safety defect on March 18, 2015.

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported