

Part 573 Safety Recall Report**15V-184****Manufacturer Name :** Motor Coach Industries**Submission Date :** MAR 25,2015**NHTSA Recall No. :** 15V-184**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Motor Coach Industries

Address : 200 East Oakton Street

Des Plaines IL 60018

Company phone : 847-285-2085

Population :

Number of potentially involved : 131

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2015 MCI J4500 and D4000ISTV, D4005, D4500, AND D4505 models

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : MCI model year 2015 D4000ISTV, D4005, D4500, D4505, and 2014 J4500 model coaches containing Meritor axles being recalled by Meritor pursuant to recall 15E-012.

Production Dates : AUG 26, 2014 - DEC 03, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Meritor reports that the tie rod end castle nuts on certain axles may not have been torqued to Meritor specifications.

Description of the Safety Risk : Meritor reports that in time the under torque condition could lose torque completely, causing the taper lock condition in the taper joint to be compromised. Loss of vehicle control is possible if the taper joint fails.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Meritor, Inc.

Address : 2135 West Maple Road
Troy FOREIGN STATES 48084

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported