

**Part 573 Safety Recall Report****15V-186****Manufacturer Name :** DS Corp DBA Crossroads RV**Submission Date :** MAR 26,2015**NHTSA Recall No. :** 15V-186**Manufacturer Recall No. :** 36**Manufacturer Information :**

Manufacturer Name : DS Corp DBA Crossroads RV

Address : 1140 W Lake Street

Topeka IN 46571

Company phone : 260-593-3850

**Population :**

Number of potentially involved : 75

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2016-2016 Crossroads Sunset Trail

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Crossroads RV Trailer

Production Dates : MAR 04, 2015 - MAR 20, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2016-2016 Crossroads Cruiser Aire

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Crossroads RV Trailer

Production Dates : MAR 04, 2015 - MAR 20, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2016-2016 Crossroads Cruiser

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Crossroads RV Trailer

Production Dates : MAR 04, 2015 - MAR 20, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2016-2016 Crossroads Cameo

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Crossroads RV Trailer

Production Dates : MAR 04, 2015 - MAR 20, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2016-2016 CrossRoads ReZerve

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : CrossRoads RV Trailer

Production Dates : MAR 04, 2015 - MAR 20, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Screws that attached the slide room mechanism are defective. Screws can fail causing mechanism to extend the slide room.

Description of the Safety Risk : If the screws fail, the slide room can extend. If the the slide room extends while the vehicle is motion a an accident can occur causing personal and/or property damage.

Description of the Cause : Crossroads was notified by Norco of the defective screws in their slide mechanism. Screws were not properly heat treated.

Identification of Any Warning that can Occur : None.

**Supplier Identification :****Component Manufacturer**

Name : Norco Division of BAL

Address : 2600 Jeanwood Dr

Elkhart INDIANA 46514

Country : United States

**Chronology :**

March 20, 2015 - Crossroads was notified by Norco of the defect in their slide room systems.

**Description of Remedy :**

Description of Remedy Program : Replace the defective screws in the slide room mechanism. This will be done at no charge to the customer.

How Remedy Component Differs from Recalled Component : None.

Identify How/When Recall Condition was Corrected in Production : Norco notified Crossroads on March 20, 2015. All production was quarantined and screws were replaced at that time. All units in shipment yard were also remedied.

**Recall Schedule :**

Description of Recall Schedule : TBD

Planned Dealer Notification Date : MAR 30, 2015 - MAR 30, 2015

Planned Owner Notification Date : MAR 30, 2015 - MAR 30, 2015

\* NR - Not Reported