

Description of the Cause : The reflector sub-assembly was inadvertently left off the motorcycle during production.
Identification of Any Warning that can Occur : An owner may visually notice that their motorcycle does not have a rear reflector.

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

FOREIGN STATES

Country : NR

Chronology :

On March 9, 2015, Harley-Davidson's Recall Investigation Committee (RIC) initiated an investigation and analysis of this issue in response to a report from our Kansas City Assembly Plant. The RIC's investigation revealed that the reflector was not being added to the motorcycle during the assembly process as required. A production ship hold on all units already produced was issued.

On March 16, 2015, a search of existing warranty data was conducted with no warranty claims, customer complaints, or crashes related to this issue.

On 04/02/15, upon review of the results of the RIC's investigation and analysis, Harley- Davidson's executive management made its determination that a noncompliance with FMVSS 108 existed in the subject population and declared a recall to remedy the issue.

Description of Remedy :

Description of Remedy Program : The rear reflector sub-assembly will be installed on the motorcycle at no cost to the customer.

How Remedy Component Differs from Recalled Component : The remedy component is the reflector sub-assembly that should have been installed during production.

Identify How/When Recall Condition was Corrected in Production : On 03/10/2015, we started installing the reflector sub-assembly during production.

Recall Schedule :

Description of Recall Schedule : Harley-Davidson will notify the dealer network on or about 04/14/2015. Customer notification letters will be sent beginning on or about 04/23/2015.

Planned Dealer Notification Date : APR 14, 2015 - APR 15, 2015

Planned Owner Notification Date : APR 23, 2015 - APR 24, 2015

* NR - Not Reported