

Part 573 Safety Recall Report**15V-228****Manufacturer Name :** Toyota Motor Engineering & Manufacturing**Submission Date :** APR 15,2015**NHTSA Recall No. :** 15V-228**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Toyota Motor Engineering & Manufact

Address : 19001 SOUTH WESTERN AVENUE

TORRANCE CA 90501

Company phone : 1-800-331-4331

Population :

Number of potentially involved : 114

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2015-2015 Toyota Scion tC

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : Although the involved vehicles are within the above VIN range, not all vehicles in this range were sold in the U.S. No other Toyota and Lexus vehicles sold in the U.S. are affected.

Production Dates : DEC 03, 2014 - JAN 30, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Toyota offers an accessory coil spring as part of an optional package that is installed at vehicle processing facilities prior to sale to dealers. For the accessory installation, the rear suspension arm bolts and nuts on the subject vehicles are removed and then re-installed. There is a possibility that the rear suspension arm bolts and nuts on some vehicles could have been tightened improperly at two of the facilities at which the accessory coil springs are installed. In this condition, the bolts could become loose during vehicle operation. Under some circumstances the rear suspension arm could eventually detach, increasing the risk of a crash.

Description of the Safety Risk : Under some circumstances the rear suspension arm could eventually detach, increasing the risk of a crash.

Description of the Cause : NR**Identification of Any Warning that can Occur :** NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

FOREIGN STATES

Country : NR

Chronology :

See attached Part 573 for chronology.

Description of Remedy :

Description of Remedy Program : All known owners of the subject vehicles will be notified by first class mail to return their vehicles to a Toyota dealer to replace the bolts, nuts, rear suspension arms and rear suspension member sub assembly. As the owner notification letters will be mailed out well within the active period of the Toyota New Vehicle Limited Warranty ("Warranty"), all involved vehicle owners for this recall would have been provided a repair at no cost under Toyota's Warranty.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Notifications to owners will begin early-June 2015. A copy of the draft owner notification letter(s) will be submitted as soon as it is available. Notifications to distributors/dealers will be sent on April 15, 2015. Copies of dealer communications will be submitted as they are issued.

Planned Dealer Notification Date : APR 15, 2015 - APR 15, 2015

Planned Owner Notification Date : NR - NR

* NR - Not Reported