

Part 573 Safety Recall Report**15V-234**

Manufacturer Name : Cruiser RV
Submission Date : APR 17,2015
NHTSA Recall No. : 15V-234
Manufacturer Recall No. : 11041R

**Manufacturer Information :**

Manufacturer Name : Cruiser RV
 Address : 7805 North State Road 9
 PO Box 130 Howe IN 46746
 Company phone : 866-277-5630

Population :

Number of potentially involved : 46
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2015 Cruiser Viewfinder

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : The liquid propane compartment in the slide room is not properly sealed to the interior of the Trailer.

Production Dates : SEP 04, 2014 - MAR 30, 2015

VIN (Vehicle Identification Number) Range

Begin : 5RXTC2629F2203486

End : 5RXTC2622G2204402

Not sequential VINs

Description of Defect :

Description of the Defect : The liquid propane compartment in the slide room is not properly sealed to the interior of the Trailer.If a leak occurred in the Liquid propane compartment the LP could be dissipated into the interior of the trailer.

Description of the Safety Risk : If Propane leaked into the interior of the RV there would be an increased risk of fire personal injury or death.

Description of the Cause : The compartment was installed inverted leaving a gap at the top which was not sealed.

Identification of Any Warning that can Occur : LP alarm should sound detection of liquid propane.

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

FOREIGN STATES

Country : NR

Chronology :

April 2, 2015 a dealer contracted an independent inspector to inspect the LP compartment.

Description of Remedy :

Description of Remedy Program : We will install a support on the interior of the RV to prevent the top from being pushed inward and seal around the opening with spray foam to seal the compartment off from the interior of the trailer.

How Remedy Component Differs from Recalled Component : The component is not being changed only the installation is being corrected.

Identify How/When Recall Condition was Corrected in Production : The metal compartment is being installed right side up and is sealed on all sides that lead into the living portion of the trailer.

Recall Schedule :

Description of Recall Schedule : Dealer notification is scheduled to begin on April 20, 2015 and end on April 21, 2015. Owner notification is scheduled to begin on shortly after approval of retail letter.

Planned Dealer Notification Date : APR 20, 2015 - APR 21, 2015

Planned Owner Notification Date : NR - NR

* NR - Not Reported