

Part 573 Safety Recall Report**15V-238**

Manufacturer Name : Highland Ridge RV
Submission Date : JUN 29,2015
NHTSA Recall No. : 15V-238
Manufacturer Recall No. : 9904237 9904238

**Manufacturer Information :**

Manufacturer Name : Highland Ridge RV
 Address : 955 Tuscany Drive
 Shipshewana IN 46565
 Company phone : 260-768-7771

Population :

Number of potentially involved : 20
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Mesa Ridge, 3X, Roamer 367FB 388RKS 427BHS

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Certain 2016 Travel Trailers and Fifth Wheels - LCI amended their list of affected chassis 5-21 - new scope for Highland Ridge Units affected as of 5-28-15
 20536-539 20544-546 20641-645 20654-660 and 20726 ALL FIFTH WHEELS

Production Dates : APR 27, 2015 - MAY 06, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : per Lippert Components - - broken studs reported on certain hubs installed on 5200# axles assemblies supplied by Tru Ryde - noting date of 3-11-2015 thru 3-27-2015 Amend: per LCI dates are only 3/13 3/17 4/10 4/13 4/14 4/15 2015

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk :Lose wheel /s could lead to high risk of crash , causing personal injury and/or property damage

Description of the Cause : Unknow to Lippert at this time.. they filed recall out of caution per LCI testing has confirmed Tempered Martensitic Embrittlement

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Lippert Components "LCI"

Address : NR

Elkhart 46515

Country : NR

Chronology :

LCI submitted list of axles serial numbers sold to Highland Ridge Rv that were affected by their recall regarding Try Ryde hubs, Highland matched to units numbers built on the axles - Lippert was on site and inspected and repaired when required all products on site and on hold in transportation lots - Highland will release recall notification to remainder of units that had shipped prior to receipt of the Lippert Recall notification. 5-21-15 LCI Amended their scope of affected Chassis and presented new list of affected chassis serial numbers. Highland has matched to product and amended 573 of file

Description of Remedy :

Description of Remedy Program : Highland Dealers will inspect the hubs on axles of the units affected and if axle date falls within the set date frame named by Lippert, the Dealer will replace the hub per Lippert's instructions at no charge to the customer.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : We are prepared to notify dealers and retail owners of the recall upon receipt of approval and recall number

Planned Dealer Notification Date : JUN 15, 2015 - JUN 15, 2015

Planned Owner Notification Date : JUN 15, 2015 - JUN 15, 2015

* NR - Not Reported