

**Part 573 Safety Recall Report****15V-238**

**Manufacturer Name :** Highland Ridge RV  
**Submission Date :** APR 20,2015  
**NHTSA Recall No. :** 15V-238  
**Manufacturer Recall No. :** 9904237 9904238

**Manufacturer Information :**

Manufacturer Name : Highland Ridge RV  
 Address : 955 Tuscany Drive  
           Shipshewana IN 46565  
 Company phone : 260-768-7771

**Population :**

Number of potentially involved : 103  
 Estimated percentage with defect : 0

**Vehicle Information :**

Vehicle : 2016-2016 Mesa Ridge, Light, Roamer 16LF,16MF,16RF, 16LT,16MR,16RT  
 Vehicle Type : TRAILERS  
 Body Style :  
 Power Train : NR  
 Descriptive Information : Certain 2016 Travel Trailers and Fifth Wheels  
 Production Dates : MAR 18, 2015 - APR 06, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : per Lippert Components - - broken studs reported on certain hubs installed on  
   5200# axles assemblies supplied by Tru Ryde - noting date of 3-11-2015 thru  
   3-27-2015

Description of the Safety Risk : Lose wheel /s could lead to high risk of crash , causing personal injury and/or  
   property damage

Description of the Cause : Unknow to Lippert at this time.. they filed recall out of caution

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Lippert Components "LCI"

Address : NR

Elkhart INDIANA 46515

Country : United States

**Chronology :**

LCI submitted list of axles serial numbers sold to Highland Ridge Rv that were affected by their recall regarding Try Ryde hubs, Highland matched to units numbers built on the axles - Lippert was on site and inspected and repaired when required all products on site and on hold in transportation lots - Highland will release recall notification to remainder of units that had shipped prior to receipt of the Lippert Recall notification.

**Description of Remedy :**

Description of Remedy Program : Highland Dealers will inspect the hubs on axles of the units affected and if axle date falls within the set date frame named by Lippert, the Dealer will replace the hub per Lippert's instructions at no charge to the customer.

How Remedy Component Differs from Recalled Component : Tru Ryde hubs w date of 3-11-2015 - 3-27-2015  
Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : We are prepared to notify dealers and retail owners of the recall upon receipt of approval and recall number

Planned Dealer Notification Date : MAY 29, 2015 - MAY 29, 2015

Planned Owner Notification Date : MAY 29, 2015 - MAY 29, 2015

\* NR - Not Reported