

Part 573 Safety Recall Report**15V-256****Manufacturer Name :** Lakota Corporation**Submission Date :** APR 29,2015**NHTSA Recall No. :** 15V-256**Manufacturer Recall No. :** 160230**Manufacturer Information :**

Manufacturer Name : Lakota Corporation

Address : PO Box 219

4 Stoutco Drive Bristol IN 46507

Company phone : 574-848-1636

Population :

Number of potentially involved : 1

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Lakota Charger C39

Vehicle Type : TRAILERS

Body Style : UNKNOWN

Power Train : NR

Descriptive Information : Lippert axles with Tru Ryde 10" or 12" hub may contain wheel studs that break. We have one trailer involved in Lippert's recall. This trailer is at Big Tex in Atkins, AR. and will not leave the dealership until parts are received from Lippert and are replaced. Dealer is aware of situation. All other affected trailers never left our facility and were corrected by Lippert prior to shipping.

Production Dates : MAR 24, 2015 - MAR 24, 2015**VIN (Vehicle Identification Number) Range**

Begin : 58JGX3G2XG1000230

End : 58JGX3G2XG1000230

 Not sequential VINs**Description of Defect :**

Description of the Defect : Wheel studs may break from wheel hub.

Description of the Safety Risk : wheel may be lost during transportation.

Description of the Cause : unknown at this time

Identification of Any Warning that can Occur : None

Supplier Identification :**Component Manufacturer**

Name : Lippert Components

Address : 1902 West Sample Street
South Bend INDIANA 46619

Country : United States

Chronology :

Lippert informed us via personal visit 4/8/15 and corrected trailers on site the next few days there after. We immediately notified 3 dealers and also sent the data to the tsb@dot.gov with the information Lippert had given us during the personal visit. The list has since changed and less trailers were affected than had originally been thought. In fact we have just one trailer affected and uncorrected.

Description of Remedy :

Description of Remedy Program : Replace wheel hubs. Lippert sending parts.

How Remedy Component Differs from Recalled Component : Lippert states the new pieces are from a different supplier.

Identify How/When Recall Condition was Corrected in Production : Lippert replaced hubs on trailers at our facility 4/8/15 with new hubs from another supplier.

Recall Schedule :Description of Recall Schedule : We have notified the dealer and they are willing to stop the jobs they are working on in their service department and replace these hubs upon receipt.
We are waiting on Lippert to send the parts.

Planned Dealer Notification Date : MAY 08, 2015 - MAY 08, 2015

Planned Owner Notification Date : NR - NR

* NR - Not Reported