

Part 573 Safety Recall Report**15V-266**

Manufacturer Name : Jayco, Inc.
Submission Date : MAY 19,2015
NHTSA Recall No. : 15V-266
Manufacturer Recall No. : 9901242

**Manufacturer Information :**

Manufacturer Name : Jayco, Inc.
 Address : 903 South Main Street
 PO Box 460 Middlebury IN 46540
 Company phone : 800-283-8267

Population :

Number of potentially involved : 2,747
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2013-2015 Seismic Pinnacle Eagle P ALL

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Affected Jayco product scope information is still under development - distribution of the recalled steps moved from HSM to Lippert Components in 11-2013 - we are currently waiting for additional information from HSM to include the steps reported by LCI to HSM that LCI sold to Jayco. We anticipate a large increase in the number of steps noted to be recalled. Units affected are 2013 and 2014 and 2015 Seismic Pinnacle and Eagle Premier fifth wheels

Production Dates : APR 03, 2013 - FEB 27, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

Not sequential VINs

Description of Defect :

Description of the Defect : Per HSM, Inc., formerly known as Hickory Springs Manufacturing, a defect exists in certain RV step models manufactured by HSM, steps were shipped between October 18, 2012 and January 9, 2015 - specific rivets in specified locations on the step may shear or pull out under load

Description of the Safety Risk : Defective rivets may allow section/s of the step to come loose and/or break off creating a safety hazard to customers.

Description of the Cause : Per HSM, the rivets are not large or strong enough to withstand a reasonable amount of weight.

Identification of Any Warning that can Occur : Per HSM, there is no visual or audible warning which would precede the failure

Supplier Identification :**Component Manufacturer**

Name : HSM, Inc

Address : 235 2nd Ave NE

Hickory NORTH CAROLINA 28604

Country : United States

Chronology :

4-20-15 Jayco received information from HSM pertaining to their recall 15E013 which include a list of POs of their recalled steps delivered to Jayco - Jayco commenced with matching the PO information to production data to create scope of affected units built with the recalled steps. During this process, was noted that LCI supplied the same recalled steps starting in 11-2013 to current and additional information would be required to create a correct scope of affected products. 5-11-15 recvd addition information from HSM adding to scope of steps.. those steps distributed by LCI affected by recall. Matched to Jayco product and included in final scope of affected units 2747

Description of Remedy :

Description of Remedy Program : HSM repair is to Replace certain rivets in specified locations with larger bolts that are rated for a much higher weight.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Jayco is prepared to contact current owner of fifth wheels to have recall repair performed at no charge by Jayco dealers upon approval.

Planned Dealer Notification Date : JUN 15, 2015 - JUN 15, 2015

Planned Owner Notification Date : JUN 15, 2015 - JUN 15, 2015

* NR - Not Reported