

Part 573 Safety Recall Report**15V-343****Manufacturer Name :** Daimler Trucks North America LLC**Submission Date :** MAY 27,2015**NHTSA Recall No. :** 15V-343**Manufacturer Recall No. :** FL-681**Manufacturer Information :**

Manufacturer Name : Daimler Trucks North America LLC

Address : 4747 N. Channel Avenue

Portland OR 97217-3849

Company phone : 800-745-8000

Population :

Number of potentially involved : 3,200

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2007-2016 Freightliner 114SD, M2 Business Class

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : See attached Cummins Westport Defect Information Report, NHTSA Recall 15E-030.

Production Dates : JAN 21, 2008 - APR 17, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2008-2009 Sterling LT8500

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : See attached Cummins Westport Defect Information Report. NHTSA Recall 15E-030

Production Dates : FEB 19, 2008 - NOV 04, 2008

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2011-2015 Thomas Built Bus Safe-T-Liner HDX

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : See attached Cummins Westport Defect Information Report. NHTSA Recall 15E-030

Production Dates : OCT 22, 2010 - NOV 22, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : See attached Cummins Westport Defect Information Report, NHTSA Recall 15E-030.

Description of the Safety Risk : See attached Cummins Westport Defect Information Report, NHTSA Recall 15E-030.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Cummins

Address : 500 Jackson St

Columbus INDIANA 47201

Country : United States

Chronology :

May 2015 – Cummins notified DTNA of NHTSA Recall 15E-030

See attached Cummins Westport Defect Information Report. NHTSA Recall 15E-030

Description of Remedy :

Description of Remedy Program : Cummins Westport is conducting this recall. Cummins Westport will install new hose clamps and ECM calibrations. Repairs will be performed by Cummins authorized service facilities. See attached Cummins Westport Defect Information Report NHTSA Recall 15E-030

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Cummins Westport will notify owners and dealers. See attached Cummins Westport Defect Information Report. NHTSA Recall 15E-030

Planned Dealer Notification Date : JUL 27, 2015 - JUL 27, 2015

Planned Owner Notification Date : JUL 27, 2015 - JUL 27, 2015

* NR - Not Reported