

**Part 573 Safety Recall Report****15V-362****Manufacturer Name :** Silver Eagle Manufacturing Company**Submission Date :** JUN 03,2015**NHTSA Recall No. :** 15V-362**Manufacturer Recall No. :** Recall No.: 15E021**Manufacturer Information :**

Manufacturer Name : Silver Eagle Manufacturing Company

Address : 5825 NE Skyport Way  
Portland OR 97218-1249

Company phone : 800-547-6792

**Population :**

Number of potentially involved : 20

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2014-2015 Silver Eagle VAST20N VAST20W CTL40W

Vehicle Type : TRAILERS

Body Style : OTHER

Power Train : NR

Descriptive Information : Possible defect of Bendix TR-3 Inversion valve

Production Dates : FEB 06, 2014 - MAR 04, 2015

**VIN (Vehicle Identification Number) Range**Begin : 1U3JV8213EBJ19479                      End : 1U3JV8216EBJ19489                       Not sequential VINsBegin : 1U3JX921XFBM19522                      End : 1U3JX9213FBM19569                       Not sequential VINsBegin : 1U3JP8725FBJ01349                      End : 1U3JP8721FBJ01350                       Not sequential VINs**Description of Defect :**

Description of the Defect : Bendix has determined that a component manufactured at a Bendix sub-supplier was not within specification limits and has led to the potential defect. This issue potentially affects a very select population of vehicles that do not have spring brakes and where the TR-3 valve is used to apply the service brake as a parking brake (primarily in dolly applications).

Description of the Safety Risk : The out-of-specification component may cause the TR-3 valve to exhaust slowly, or not fully exhaust, leading to the potential overheating of vehicle brakes and potential fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : The driver may detect partially applied service brakes while driving by feeling an increased resistance in the vehicle drivetrain or sensing an odor caused by overheated brakes.

**Supplier Identification :**

**Component Manufacturer**

Name : Bendix Commerical Vehicle Systems LLC

Address : 16416 NE 26th Avenue

Ridgefield WASHINGTON 98642

Country : United States

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : Replace the existing TR-3 Valve with a Sliver Eagle Part Number 34192 recall kit (Bendix Part Number K123677)

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : JUN 10, 2015 - JUN 15, 2015

\* NR - Not Reported