

Part 573 Safety Recall Report**15V-369**

Manufacturer Name : Forest River, Inc.
Submission Date : MAY 11, 2016
NHTSA Recall No. : 15V-369
Manufacturer Recall No. : 54-06052015-0047

**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.
 Address : 55470 CR 1
 P.O. Box 3030 Elkhart IN 46515-3030
 Company phone : 1-800-348-7440

Population :

Number of potentially involved : 249
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2015 Shasta Airflyte SAT16 and SAT19
 Vehicle Type : TRAILERS
 Body Style : OTHER
 Power Train : NR
 Descriptive Information : Recreational Travel trailer
 Production Dates : SEP 15, 2014 - OCT 22, 2014

VIN (Vehicle Identification Number) Range

Begin : 5ZT2SAEC9FE610002 End : 5ZT2SAEC6FE610426 Not sequential VINs

Description of Noncompliance :

Description of the Noncompliance : The tires and GAWR on the trailer do not match the tire information label, Federal Certification label.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : The tires will be overloaded if the unit is loaded to the GAWR of the labels. The tires may blow out, causing loss of control, crash, property damage and possible injury or death.

Description of the Cause : The tires on the trailer are P225/75R15 @ 35PSI which are de-rated to 1704. The labels indicate ST225/75R15/D tires rated at 2540.

Identification of Any Warning that can Occur : The tire will blow out.

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On May 14, 2015, Forest River was contacted by NHTSA concerning an investigation of a potential noncompliance where a customer's trailer did not correctly list tire size and tire pressure on the Tire and Loading Information placard that did not match the tires installed on the unit. Forest River believed this to be an isolated event and the division prepared and issued a new label to the owner of the trailer. Upon review of the records for all units produced from 9/15/2014 to 5/22/2015, it was found that there were 249 US units that had the incorrectly listed tire information.

Description of Remedy :

Description of Remedy Program : We will supply each owner and dealer with a corrected set of labels to replace the incorrect labels on the trailer. The customer may install them themselves or take the unit and the labels to their dealer to have the labels replace at no charge to the customer. We will reimburse the dealer under our standard warranty program.

How Remedy Component Differs from Recalled Component : The remedy component will have the correct tire, PSI, GAWR, GVWR and Cargo Carrying Capacity compatible with the tires mounted on the trailer.

Identify How/When Recall Condition was Corrected in Production : The master computer system was corrected 10/22/2014 with the proper information.

Recall Schedule :

Description of Recall Schedule : As soon as Forest River receives a recall number from NHTSA we will submit a list of VIN numbers to R. L. Polk for the latest owner names and addresses. This usually takes about 10 days from submittal.

Planned Dealer Notification Date : JUN 19, 2015 - JUN 19, 2015

Planned Owner Notification Date : JUN 29, 2015 - JUN 29, 2015

* NR - Not Reported