

Part 573 Safety Recall Report**15V-386****Manufacturer Name :** Jaguar Land Rover North America, LLC**Submission Date :** JUN 11,2015**NHTSA Recall No. :** 15V-386**Manufacturer Recall No. :** P065**Manufacturer Information :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Address : 555 MACARTHUR BOLULEVARD
MAHWAH NJ 07430

Company phone : 201-760-8534

Population :

Number of potentially involved : 492

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2012-2013 Land Rover LR4

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : Land Rover LR4 SUV in select VIN range

Production Dates : AUG 15, 2012 - SEP 18, 2012

VIN (Vehicle Identification Number) Range

Begin : SALAG2D47CA642568

End : SALAK2D4XDA646811

 Not sequential VINs**Description of Defect :**

Description of the Defect : A concern has been identified on certain Land Rover LR4 2012-2013 Model Year vehicles where the panoramic roof adhesive and primer used in the assembly bonding of the panoramic roof glass panel may not have been to the correct specification.

Customers have reported the panoramic roof assembly was either noisy, loose, leaking water into the vehicle or, in one case, had detached from the vehicle while the vehicle was in motion.

Description of the Safety Risk : Where the panoramic roof glass panel detaches from the vehicle, it may collide with other vehicles on the road or compel other road users to take evasive action. This could increase the risk of a vehicle crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NSG Group

Address : Eckersall Road

Kings Norton Birmingham FOREIGN STATES B38 8SR

Country : United Kingdom

Chronology :

Attachment

Description of Remedy :

Description of Remedy Program : Owners will be instructed to take their vehicle to a Land Rover dealer who will re-apply the correct primer to the panoramic roof assembly.

There will be no charge to owners for this repair.

Customer who have paid for a repair of this defect will be subject to the Jaguar Land Rover reimbursement plan subject to meeting the current terms and conditions.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Dealer/Owner dates as given.

Planned Dealer Notification Date : JUN 16, 2015 - JUN 16, 2015

Planned Owner Notification Date : AUG 07, 2015 - AUG 07, 2015

* NR - Not Reported