

Part 573 Safety Recall Report**15V-401**

Manufacturer Name : Cruiser RV
Submission Date : JUN 18,2015
NHTSA Recall No. : 15V-401
Manufacturer Recall No. : 11043R & 11044R

**Manufacturer Information :**

Manufacturer Name : Cruiser RV
 Address : 7805 North State Road 9
 PO Box 130 Howe IN 46746
 Company phone : 866-277-5630

Population :

Number of potentially involved : 13
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Cruiser Stryker
 Vehicle Type : TRAILERS
 Body Style :
 Power Train : NR
 Descriptive Information : model designations of ST2912 and STG3010
 Production Dates : MAR 23, 2015 - APR 20, 2015

VIN (Vehicle Identification Number) Range

Begin : 5RXTG2924G2204367 End : 5RXTG3026G2204504 Not sequential VINs

Description of Defect :

Description of the Defect : It has been decided the vehicles identified in this recall population equipped with axles manufactured by Lippert Components Inc. (LCI) and Tru Ryde or Axle Tek 10" or 12" wheel hubs may have been manufactured with wheel studs which could break. The axles can be identified by the first three (3) digits of the axle tag serial number, manufacturing date and the Tru Ryde name or the Axle Tek name stamped on the wheel hub face. LCI Indiana Plant 45 – Serial # beginning with 045 with manufacturing dates from 03/11/15 thru 03/27/15 with 12" Tru Ryde wheel hubs or manufacturing dates from 04/10/15 thru 04/15/15 with 12" Axle Tek wheel hubs. LCI Idaho Plant 57 – Serial # beginning with 057 with manufacturing dates 03/20/15 thru 04/09/15 with 10" or 12" Tru Ryde wheel hubs.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If more than one wheel stud breaks and the vehicle is in motion, it could result in the separation of the wheel from the vehicle leading to an increased risk of property damage and/or vehicle crash.

Description of the Cause : The cause of the studs breaking is due to Tempered Martensitic Embrittlement.

Identification of Any Warning that can Occur : Wheel studs may be missing.

Supplier Identification :**Component Manufacturer**

Name : Lippert Components Inc.

Address : 1902 West Sample St.
South Bend 46616

Country : NR

Chronology :

4/20/2015 – Cruiser RV contacted by LCI stating that potential defective axles were delivered to Cruiser RV.

4/20/2015 – LCI on site at Cruiser RV to locate and inspect all axles in the scope given at that time. All axles were located and inspected and none were found to be defective in this scope.

4/23/2015 – LCI contacts Cruiser RV that the scope has changed slightly and further investigation is required. All axles located and inspected. Defective axles replaced. No recall issued based on investigation and corrective action.

5/22/2015 – LCI contacts Cruiser RV with yet another scope of defective axles. Cruiser begins investigation on new scope of potentially defective axles

6/2/2015 – Cruiser RV locates all axles and makes the decision to issue a recall for those units that have made it into the field and are out of Cruiser RV's possession.

Description of Remedy :

Description of Remedy Program : The wheel hubs will be inspected and replaced if identified as per the prior description.

How Remedy Component Differs from Recalled Component : The remedy components were manufactured by other suppliers or a different production lot.

Identify How/When Recall Condition was Corrected in Production : All loose axle inventories were quarantined and then replaced with axles produced with wheels studs from a different lot. Completed vehicles with axles built within the specified date range and with the Tru Ryde or Axle Tek wheel hub were identified and the wheel hubs were replaced

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JUN 22, 2015 - JUN 22, 2015

Planned Owner Notification Date : JUN 24, 2015 - JUN 24, 2015

* NR - Not Reported