

Part 573 Safety Recall Report**15V-434****Manufacturer Name :** Allied Recreation Group, Inc.**Submission Date :** JUL 01,2015**NHTSA Recall No. :** 15V-434**Manufacturer Recall No. :** 150625ARG**Manufacturer Information :**

Manufacturer Name : Allied Recreation Group, Inc.

Address : 1031 U.S. 224 E

P.O. Box 31 Decatur IN 46733

Company phone : 800 509 3417

Population :

Number of potentially involved : 32

Estimated percentage with defect : 45

Vehicle Information :

Vehicle : 2015-2016 Fleetwood Southwind 32 VS

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : Class A motorhomes

Production Dates : APR 16, 2014 - JUN 19, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Noncompliance :**

Description of the Noncompliance : On motor homes affected by this recall, an emergency egress window was not installed in the road side bedroom wall, thus failing to comply with ANSI/NFPA 1192 Standard, Section 6.2.1, "Means of Escape".

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If there is no emergency egress window in the bedroom, escape from the motor home may be delayed or prevented, increasing the risk of personal injury in the event of a fire or other emergency. The window can be displaced with less than 25 lbs-Force which maybe considered excessive.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

ARG began an investigation on June 25, 2015, when during a routine audit inspection of a 2016 Southwind 32 VS it was determined to have the incorrect window specified that would normally be in the egress position of this particular model.

A review of ARG's manufacturing records indicated the incorrect windows were first received and installed in Southwind model

32 VS during model year 2015 production. ARG is not aware of any accidents or injuries which have resulted from this noncompliance.

Description of Remedy :

Description of Remedy Program : ARG dealers will inspect, and if necessary, replace the existing road side bedroom window with an emergency egress window.

Pursuant to 49 CFR 577.11(e) ARG does not plan to provide reimbursement notification to owners because all involved vehicles are covered under the new vehicle warranty.

How Remedy Component Differs from Recalled Component : The emergency egress window can be identified by red exit handles, which are visible from the inside of the window.

Identify How/When Recall Condition was Corrected in Production : As of June 25, 2015, all potentially affected units were inspected, and if necessary, repaired before shipment. All future production runs will be manufactured using the correct window.

Recall Schedule :

Description of Recall Schedule : ARG intends to conduct a dealer notification by e-mail in August 2015. ARG intends to conduct a customer notification by US mail in August 2015. ARG does not foresee any problems with implementing this voluntary recall campaign.

Planned Dealer Notification Date : AUG 14, 2015 - AUG 14, 2015

Planned Owner Notification Date : AUG 18, 2015 - AUG 18, 2015

* NR - Not Reported