

Part 573 Safety Recall Report**15V-472****Manufacturer Name :** Honda (American Honda Motor Co.)**Submission Date :** JUL 23,2015**NHTSA Recall No. :** 15V-472**Manufacturer Recall No. :** JT2, JT4**Manufacturer Information :**

Manufacturer Name : Honda (American Honda Motor Co.)

Address : 1919 Torrance Blvd.

Torrance CA 90501

Company phone : 310-783-2000

Population :

Number of potentially involved : 11,506

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2016-2016 HONDA HR-V

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population was determined based on manufacturing records. The VIN range reflects all possible vehicles that could potentially experience the problem.

Production Dates : JAN 12, 2015 - MAY 20, 2015

VIN (Vehicle Identification Number) Range

Begin : 3CZRU5H37GM700025

End : 3CZRU5H72GM708861

 Not sequential VINs

Begin : 3CZRU6H73GM700015

End : 3CZRU6H53GM712020

 Not sequential VINs**Description of Defect :**

Description of the Defect : The required tire placard indicating "Tire and Loading Information" may not have been applied during vehicle assembly.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : Non-compliance with S4.3 of FMVSS 110

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

April 14, 2015

Inspection of vehicles at the delivery port in San Diego produced one vehicle missing a tire placard.

May 19, 2015

Another vehicle was found at the delivery port missing the tire placard label. Immediate action began on repairs and containment at the factory and shipping ports. Investigation also began to determine if affected units had been shipped to dealers.

July 16, 2015

Honda Motor Company completed the investigation and determined that non-compliance exists and a non-compliance recall will be conducted.

As of July 16, 2015 Honda has not received any warranty claims, field reports or injuries related to this issue.

Description of Remedy :

Description of Remedy Program : The owners of all affected vehicles will be contacted by mail and asked to take their vehicle to a Honda automobile dealer. The dealer will inspect the label and apply a corrective label free of charge.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JUL 23, 2015 - NR

Planned Owner Notification Date : SEP 18, 2015 - SEP 18, 2015

* NR - Not Reported