

# Part 573 Safety Recall Report

# 15V-477

**Manufacturer Name :** Newmar Corporation**Submission Date :** MAY 06, 2016**NHTSA Recall No. :** 15V-477**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

**Population :**

Number of potentially involved : 472

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2007-2009 Newmar All Star

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the exterior fuel dispensing system compartment on toy hauler motorhomes has the possibility of being in contact with flammable material. The inside top of the compartment shows the bottom of the flooring which has flammable plastic wrap showing. If the exterior fuel dispensing compartment started a fire, the plastic wrap could burn which may increase the risk of a fire or a crash.

Production Dates : JAN 30, 2006 - OCT 21, 2009

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2009-2016 Newmar Canyon Star

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the exterior fuel dispensing system compartment on toy hauler motorhomes has the possibility of being in contact with flammable material. The inside top of the compartment shows the bottom of the flooring which has flammable plastic wrap showing. If the exterior fuel dispensing compartment started a fire, the plastic wrap could burn which may increase the risk of a fire or a crash.

Production Dates : NOV 28, 2007 - JUL 09, 2015

VIN Range 1 : Begin :

NR

End : NR

 Not sequential**Description of Defect :**

**Description of the Defect :** On certain motorhomes, the exterior fuel dispensing system compartment on toy hauler motorhomes has the possibility of being in contact with flammable

material. The inside top of the compartment shows the bottom of the flooring which has flammable plastic wrap showing. If the exterior fuel dispensing compartment started a fire, the plastic wrap could burn which may increase the risk of a fire or a crash.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the exterior fuel dispensing compartment started a fire, the plastic wrap could burn which may increase the risk of a fire or a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

## Supplier Identification :

### Component Manufacturer

Name : Newmar Corporation

Address : 355 N. Delaware ST.

Nappanee INDIANA 46550

Country : United States

## Chronology :

7/24/2015 Newmar Corporation is reporting a recall campaign concerning specific Newmar Toy Hauler motorhomes identified as potentially defective by Newmar Corporation.

07/28/2015 Newmar sent Notice of Defect to NHTSA.

07/30/2015 Customer and Dealer letters were sent out for notification.

## Description of Remedy :

Description of Remedy Program : Newmar Corporation will be conducting this recall in its entirety. Metal will be added to the top of the exterior fuel compartment protecting the plastic wrap. This will be done at no charge. Work instructions will be issued to Newmar dealers.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : SEP 26, 2015 - NR

Planned Owner Notification Date : SEP 26, 2015 - NR

\* NR - Not Reported