

**Part 573 Safety Recall Report****15V-492****Manufacturer Name :** Newmar Corporation**Submission Date :** JUL 31,2015**NHTSA Recall No. :** 15V-492**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

**Population :**

Number of potentially involved : 82

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2015-2015 Newmar Essex and King Aire

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** On certain units, the control module for the air suspension may experience a loss of power resulting in the air suspension not being able to achieve ride height. If the ride height of the suspension is less than specified ride height, negative impact to roll steer could occur. This could cause the vehicle to be difficult to control and increase the risk of a crash. This could occur without warning.

Production Dates : MAR 07, 2014 - JUN 15, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs

Vehicle : 2016-2016 Newmar Mountain Aire; Essex and King Aire

Vehicle Type :

Body Style :

Power Train : NR

**Descriptive Information :** On certain units, the control module for the air suspension may experience a loss of power resulting in the air suspension not being able to achieve ride height. If the ride height of the suspension is less than specified ride height, negative impact to roll steer could occur. This could cause the vehicle to be difficult to control and increase the risk of a crash. This could occur without warning.

Production Dates : MAR 09, 2015 - JUN 05, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : On certain units, the control module for the air suspension may experience a loss of power resulting in the air suspension not being able to achieve ride height. If the ride height of the suspension is less than specified ride height, negative impact to roll steer could occur. This could cause the vehicle to be difficult to control and increase the risk of a crash. This could occur without warning.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the ride height of the suspension is less than specified ride height, negative impact to roll steer could occur. This could cause the vehicle to be difficult to control and increase the risk of a crash. This could occur without warning.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Spartan Motors, Inc.

Address : NR

NR

Country : NR

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported