

Part 573 Safety Recall Report**15V-495**

Manufacturer Name : Starcraft RV
Submission Date : AUG 07,2015
NHTSA Recall No. : 15V-495
Manufacturer Recall No. : 9902246

**Manufacturer Information :**

Manufacturer Name : Starcraft RV
 Address : 903 South Main Street
 P.O. Box 460 Middlebury IN 46540
 Company phone : 800-945-4787

Population :

Number of potentially involved : 705
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2015-2016 Launch Ultra Lite TT "JT" 24 RLS
 Vehicle Type : TRAILERS
 Body Style :
 Power Train : NR
 Descriptive Information : F2JT5171 - 5522 and G2JT5051 - 5499
 Production Dates : JUN 17, 2014 - JUL 23, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : The furnace may not be properly secured to the unit

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Excess movement of the furnace may allow the furnace to pull loose from the exhaust and allow hazardous fumes to escape into the travel trailer

Description of the Cause : Improper Installation on the production line.

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

During a routine production line audit July 29, 2015, it was discovered that the vertically installed furnace in a 2016 24RLS Launch Ultra Lite Travel Trailer was not properly secured to the unit. Production immediately commenced with investigation and placed all JT units on hold until inspected. Inspection of all units on site established that production line had not been consistent on how it secured the furnace to the floor of the travel trailer when installing. Subsequently a decision was made to file a recall due to the possibility of a safety hazard being present, if the furnace was to pull away from the exhaust.

Description of Remedy :

Description of Remedy Program : Starcraft Dealers will inspect the travel trailer for the proper securing of the furnace, if found to be incorrect, Dealers will secure the furnace correctly with the required bracket and screws to attach the furnace to the floor platform of the unit .

How Remedy Component Differs from Recalled Component : Location of the bracket secured to the furnace and floor.

Identify How/When Recall Condition was Corrected in Production : July 29, 2015 the current production line of the JT Launch Ultra Lite Corrected the position of the bracket securing the furnace to unit floor.

Recall Schedule :

Description of Recall Schedule : Starcraft is prepared to contact current owners of affected units immediately upon NHTSA's approval.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported