

Part 573 Safety Recall Report**15V-535****Manufacturer Name :** Strick Trailers, LLC**Submission Date :** SEP 17,2015**NHTSA Recall No. :** 15V-535**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Strick Trailers, LLC

Address : 301 North Polk Street
Monroe IN 46772

Company phone : 260-692-1300

Population :

Number of potentially involved : 4

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2014-2014 Strick L7450E48NSOW, S7480E99NSOWL, M7320E99NFWO

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Vehicles built with CBX Series trailer suspension air ride axle system manufactured by SAF-HOLLAND, Inc. and shipped between September 29, 2013 and November 30, 2013 containing:

Serial no. 51133020123 and material no. S02BJ1588-0023

Serial no. 51132740297 and material no. S02AA0203-0000

Serial no. 51132800475 and material no. S17CN0037-5000

Serial no. 51132800476 and material no. S17CN0037-5000

Serial no. 51132800477 and material no. S17DB0037-5000

Serial no. 51132800478 and material no. S17DB0037-5000

Production Dates : NOV 12, 2013 - DEC 09, 2013

VIN (Vehicle Identification Number) Range

Begin : 1S12E9454EE529573

End : 1S12E9454EE529573

 Not sequential VINs

Begin : 1S12E9483EE529736

End : 1S12E9483EE529736

 Not sequential VINs

Begin : 1S12E9328EE529759

End : 1S12E9324EE529760

 Not sequential VINs**Description of Defect :**

Description of the Defect : The defect involves pivot bolts on SAF-HOLLAND CBX Series trailer suspension air ride axle systems. The defect has been identified as an intergranular quench crack at the point where the bolt head meets the body of the bolt.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Separation of the axle/suspension assembly from the trailer is possible if both

sides of the pivot connection fail resulting in the trailer becoming misaligned behind the tractor which could result in a crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : SAF-HOLLAND, Inc.

Address : 1950 Industrial Boulevard
Muskegon MICHIGAN 49443

Country : United States

Chronology :

On or about June 24, 2014 Strick learned that Stoughton Trailers, LLC was conducting a recall due to a possible defect that could lead to a suspension system or axle manufactured by SAF-HOLLAND separating from its manufactured trailers. On June 27, 2014 a representative from SAF-HOLLAND contacted Strick confirming that a safety recall had been initiated by SAF-HOLLAND. On July 22, 2014, Strick received a Notice of Safety Recall from SAF-HOLLAND, Inc. On July 28, 2014 Strick filed a recall report with NHTSA and our campaign was assigned recall no. 14V-497.

On August 12, 2015 Strick received a Notice of Safety Recall from SAF-HOLLAND, Inc. advising that its initial recall campaign no. 14E-024 was being replaced by recall campaign no. 15E-061 as the date range of the initial recall campaign was being expanded to include CBX Suspensions, repair kits and loose bolts shipped to Strick between September 20, 2013 and October 8, 2013. The additional shipping days expanded the original date range of October 8, 2013 to November 30, 2013. Consequently, additional trailers are now impacted by this replacement recall campaign no. 15E-061.

Description of Remedy :

Description of Remedy Program : "Service Bulletin" and "Repair Instruction" issued by SAF-HOLLAND, Inc. will be attached as a separate document.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : The proposed form of customer notification letter will be provided to NHTSA for approval within 45 days from the date hereof.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : SEP 17, 2015 - SEP 17, 2015

* NR - Not Reported