

Part 573 Safety Recall Report**15V-630****Manufacturer Name :** Volvo Trucks North America**Submission Date :** OCT 03,2015**NHTSA Recall No. :** 15V-630**Manufacturer Recall No. :** RVXX1505**Manufacturer Information :**

Manufacturer Name : Volvo Trucks North America

Address : 7900 National Service Road

Greensboro NC 27409

Company phone : 800 528 6586

Population :

Number of potentially involved : 1,669

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2015-2016 Volvo VAH, VHD

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : VAH and VHD manufactured from April 1, 2015 through August 14, 2015.

Percentage of headlamps that are not compliant is unknown

Production Dates : APR 01, 2014 - AUG 14, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Noncompliance :**

Description of the Noncompliance : According to OSRAM, "The subject headlamps may not meet the minimum intensity requirements at certain test points as specified in FMVSS No. 108, S10.13.3 and Tables XVIII and XIX-b."

FMVSS 1 : 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2 : NR

Description of the Safety Risk : Also according to OSRAM, "These headlamps may not provide sufficient illumination of distant objects or the roadway. Insufficient illumination could result in a vehicle crash."

Volvo has not received reports of vehicle crashes.

Description of the Cause : A manufacturing issue

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Osram Sylvania Products, Inc

Address : 100 Endicott Street

Danvers MASSACHUSETTS 01923

Country : United States

Chronology :

5/29/15 Testing conducted by Volvo suggests that there may be a non-compliance with sealed beam headlamps provided in an assembly provided to Volvo by Koito. Information provided to Koito, who opens an investigation

7/10/15 Koito provides updates Volvo on progress of investigation

8/25/15 Koito receives draft customer notification letter from OSRAM

8/26/15 Koito shares draft customer notification letter with Volvo

9/14/15 Information provided to help identify trucks that may be affected

9/28/15 Scope identified

10/3/15 Volvo informs NHTSA that a voluntary safety recall will be conducted to address trucks that may have been manufactured with a non-compliant sealed beam headlamp

Description of Remedy :

Description of Remedy Program : Replace the headlamps. Reimbursement for cost incurred by the owner for "prenotification remedies" will be addressed on a case-by-case basis according to the "General Plan for Reimbursement of Pre-notification Remedies" which was published October 28, 2013.

How Remedy Component Differs from Recalled Component : The headlamps are compliant at all test points

Identify How/When Recall Condition was Corrected in Production : August 17, Compliant headlamps

Recall Schedule :

Description of Recall Schedule : Dealers will be notified by October 8, 2015 with owner notification by December 3, 2015

Planned Dealer Notification Date : OCT 08, 2015 - OCT 08, 2015

Planned Owner Notification Date : DEC 03, 2015 - DEC 03, 2015

* NR - Not Reported