

Part 573 Safety Recall Report**15V-638****Manufacturer Name :** Starcraft RV**Submission Date :** OCT 07,2015**NHTSA Recall No. :** 15V-638**Manufacturer Recall No. :** 9902258**Manufacturer Information :**

Manufacturer Name : Starcraft RV

Address : 903 South Main Street

P.O. Box 460 Middlebury IN 46540

Company phone : 800-945-4787

Population :

Number of potentially involved : 35

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Travel Trailer Autumn Ridge

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : G2895051 thru G2895085

Production Dates : MAR 27, 2015 - SEP 22, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Frame was built incorrectly causing inadequate clearance between wheel and wheel well

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : could allow tire wear and/or blow out

Description of the Cause : March 2015 Jayco submitted Incorrect print to manufacture of frame for this model - print omitted a 2" tube that was to be added to the I beam -

Identification of Any Warning that can Occur : rubbing / wear on tire

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

10-2-15 Starcraft discovered during normal audit, that the clearance was not correct on the 2016 Autumn Ridge 339BHTS model of the Octane travel trailer. All 339BHTS Octanes on site were inspected and found to ALL have inadequate clearance between the wheel and wheel well. Investigation of the Location of all 2016 Octanes affected, found 6 already shipped to Dealers and 1 retailed sold with balance being placed on HOLD to prevent shipping. Dealers in possession of affected units, were called by Service Group and told to Place the unit on hold due to upcoming recall and NOT to retail sale the unit till repair was released by Starcraft. Starcraft is also faxing the same information to each dealer. We are currently trying to reach the retail owner of the unit by phone, and are also sending a letter ahead of the official release of the recall.

Description of Remedy :

Description of Remedy Program : not know at this time - Starcraft is working with frame manufacture for the field repair.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Correct print submitted to LCI - frame manufacture on 10-2-2015 All future frames will be correct

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported