

Part 573 Safety Recall Report**15V-663****Manufacturer Name :** Chrysler (FCA US LLC)**Submission Date :** OCT 15,2015**NHTSA Recall No. :** 15V-663**Manufacturer Recall No. :** R58**Manufacturer Information :**

Manufacturer Name : Chrysler (FCA US LLC)

Address : 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI 48326-2757

Company phone : 1-800-853-1403

Population :

Number of potentially involved : 253

Estimated percentage with defect : 33

Vehicle Information :

Vehicle : 2016-2016 Ram 1500

Vehicle Type :

Body Style : PICKUP TRUCK

Power Train : NR

Descriptive Information : Certain 2016 MY RAM 1500 Trucks

Production Dates : AUG 03, 2015 - AUG 10, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Some 2016 MY Ram 1500 pickup trucks with a 5.7L engine with dual exhaust may be missing a spare tire heat shield which may allow damage to the spare tire.

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : If a spare tire is damaged and in use, the spare tire may experience rapid air loss due to tread separation or side wall rupture potentially resulting in a loss of control condition .

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

Please see attached supplemental information titled " FCA US LLC Chronology – R58 2016 RAM 1500 Missing Spare Tire Heat Shield 10152015.pdf"

Description of Remedy :

Description of Remedy Program : FCA US will conduct a Voluntary Safety Recall on all affected vehicles to inspect for the presence of a passenger side spare tire heat shield. If the passenger side spare tire heat shield is not present, a heat shield will be installed. If a passenger side spare tire heat shield is being installed on a sold truck, the spare tire will be replaced; Removed spare tires will be altered to prevent use or sale. If a passenger side spare tire heat shield is being installed on an un-sold truck, the spare tire will not be replaced as it has not been exposed to use conditions.

FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : FCA US will provide a dealer notification and owner notification schedule once established

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported