

**Part 573 Safety Recall Report****15V-680****Manufacturer Name :** Starcraft RV**Submission Date :** NOV 04,2015**NHTSA Recall No. :** 15V-680**Manufacturer Recall No. :** 9902060**Manufacturer Information :**

Manufacturer Name : Starcraft RV

Address : 903 South Main Street

P.O. Box 460 Middlebury IN 46540

Company phone : 800-945-4787

**Population :**

Number of potentially involved : 985

Estimated percentage with defect : 100

**Vehicle Information :**

Vehicle : 2015-2016 Travel Trailers Launch Launch Ultra,AR-One, AR-One Maxx Autumn Ridge Travel Star

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : ALL MODELS/ UNITS MANUFACTURED ON LINE 58 in noted  
production dates

Production Dates : JUL 09, 2015 - OCT 02, 2015

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**Description of the Defect : Breaker box - breakers mislabeled or missing labels 10-14-15 adding 12V fuse  
panel also has incrt information on label.. states all are 15 amp fuses, when there is  
one 20 amp fuse

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : possibility of electrical shock if breaker is closed for wrong area when working  
on coach.Description of the Cause : Human error on production line - correct diagram showing placement was not  
followed

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

**Chronology :**

10-2-15 - during inspection on production line, was discovered that the breakers in a breaker box were mislabeled or they didn't have a label at all. Investigation/ inspection of all products on all lines started immediately. Discovered that line workers were not following print showing correct labeling.. we are still trying to determine the starting point of the affected units 10-7-15 production discovered that the 12V fuse panel on these units is labeled that all fuse are 15 amp but one is a 20amp. will include both issues on one recall instructions.

**Description of Remedy :**

Description of Remedy Program : StarCraft will send Current Owners - retail and dealers- correct labels for all breakers and 12 v fuse panel w instructions showing correct location - Starcraft has labels and has correct all products on site prior to shipping.  
10-14-15 Adding new label will be provided for the 12V fuse panel

How Remedy Component Differs from Recalled Component : correct location of labels

Identify How/When Recall Condition was Corrected in Production : 10-2-15 all production lines were checked to make sure line workers were following print and placing labels correctly in breaker box.

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported