

**Part 573 Safety Recall Report****15V-722****Manufacturer Name :** Transportation Collaborative, Inc.**Submission Date :** OCT 30,2015**NHTSA Recall No. :** 15V-722**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Transportation Collaborative, Inc.

Address : 7 Lake Station Road

Warwick NY 10990

Company phone : 845-988-0419

**Population :**

Number of potentially involved : 0

Estimated percentage with defect : 0

**Vehicle Information :**

Vehicle : 2006-2015 Trans Tech Bus Student Safety Transporter

Vehicle Type : BUSES, MEDIUM &amp; HEAVY VEHICLES

Body Style : OTHER

Power Train : NR

Descriptive Information : Ricon Corporation Recall 15E-068 - Platform Pivot Plate Fracturing

Production Dates : JAN 01, 2006 - APR 21, 2014

**VIN (Vehicle Identification Number) Range**

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Under certain conditions present in some applications, the platforms included on the S-Series model wheelchair lifts as manufactured by the Ricon Corporation can exhibit cracking of the platform pivot plate while in the stowed position which, if left unchecked, can propagate to the point where separation of the rear portion of the pivot plate occurs rendering the lift potentially inoperable and possibly unsafe for the operator.

FMVSS 1 : NR

FMVSS 2 : 403 - Platform lift systems

Description of the Safety Risk : In the event the aforementioned crack occurs on both sides of the platform and is allowed to propagate to the point of material separation on both sides it is possible for the lift platform to lean against the vehicle lift door(s) and fall out of the vehicle when the door(s) is(are) opened, putting the lift operator at risk.

Description of the Cause : To be determined.

Identification of Any Warning that can Occur : Fracturing on both sides of the pivot platform plate and other visually apparent changes to the pre-existing assembly.

**Supplier Identification :**

**Component Manufacturer**

Name : Ricon Corporation

Address : 1135 Aviation Place

San Fernando CALIFORNIA 91340

Country : United States

**Chronology :**

NR

**Description of Remedy :**

Description of Remedy Program : NR

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

\* NR - Not Reported