

Part 573 Safety Recall Report**15V-741**

Manufacturer Name : Forest River, Inc.
Submission Date : NOV 06,2015
NHTSA Recall No. : 15V-741
Manufacturer Recall No. : 37-11052015-0106

**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.
 Address : 55470 CR 1
 P.O. Box 3030 Elkhart IN 46515-3030
 Company phone : 219-533-5934

Population :

Number of potentially involved : 67
 Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2016-2016 Forest River, Inc. Surveyor - SVT243RBS

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Surveyor is a recreational vehicle trailer that is manufactured by Forest River, Inc.

Production Dates : JUN 25, 2015 - NOV 02, 2015

VIN (Vehicle Identification Number) Range

Begin : 4X4TSVZ22GL026823

End : 4X4TSVZ21GL027736

Not sequential VINs

Vehicle : 2010-2016 Forest River, Inc. Surveyor - ORSVT243RBS

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Surveyor is a recreational vehicle trailer that is manufactured by Forest River, Inc.

Production Dates : JUL 31, 2015 - OCT 23, 2015

VIN (Vehicle Identification Number) Range

Begin : 4X4TSVZ22G2474422

End : 4X4TSVZ25G2474477

Not sequential VINs

Description of Noncompliance :

Description of the Noncompliance : The noncompliance is the Federal placard indicating the tire size and rim size has been incorrectly stated. The Federal placard states a ST225/75R15C tire and rim where installed onto the vehicle. However, the actual installed tire and rim is ST205/75R14C.

FMVSS 1 : 567 - Certification

FMVSS 2 : NR

Description of the Safety Risk : The risk involved is if an individual solely derived the tire and rim size from the Federal placard, the individual would install an over-sized tire that will bear more load than the rest of the tires. This would lead to ill handling of the vehicle, potential for tire contact with the floor or wheel-well, reduced life of the bearings in all of the hubs as the vehicle would be out of alignment, and potential loss of the tire. This will also increase the risk of a crash.

Description of the Cause : Inaccurate information flow from the manufacturing plant to engineering of which tire should be on the Federal Placard.

Identification of Any Warning that can Occur : A warning would only be indicated from the comparison of the Federal placard to the physical tire itself.

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

The manufacturing plant notified the Office of Corporate Compliance (“OCC”) on November 2, 2015 that the Federal placard stated the incorrect tire and rim data. On November 2, 2015, the Recall Committee convened and reviewed this topic. The Committee decided to recall the vehicle because the Federal placard violated the FMVSS 567. OCC will be receiving new Federal tags to send to the Forest River dealers.

Description of Remedy :

Description of Remedy Program : Forest River, Inc. will provide, free of charge the new Federal placard that indicates the correct tire and rim combination.

How Remedy Component Differs from Recalled Component : The new Federal placard issued by OCC will indicate the correct tire and rim combination.

Identify How/When Recall Condition was Corrected in Production : On November 5, 2015, the manufacturing plant provided a revised weight sheet with the corrected tire size and rim combination to engineering and entered into the corporate weight system.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River has sent suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : DEC 31, 2015 - DEC 31, 2015

Planned Owner Notification Date : DEC 31, 2015 - DEC 31, 2015

* NR - Not Reported