

Part 573 Safety Recall Report**15V-774****Manufacturer Name :** Utility Trailer Manufacturing Company**Submission Date :** NOV 17,2015**NHTSA Recall No. :** 15V-774**Manufacturer Recall No. :** 15E083**Manufacturer Information :**

Manufacturer Name : Utility Trailer Manufacturing Company

Address : 17295 E. Railroad Street

City Of Industry CA 91748-1022

Company phone : 818-965-1541

Population :

Number of potentially involved : 10

Estimated percentage with defect : 0

Vehicle Information :

Vehicle : 2015-2015 Refrigerated Van VS2RA

Vehicle Type : TRAILERS

Body Style : VAN

Power Train : NR

Descriptive Information : Refrigerated vans manufactured by Utility Trailer Manufacturing out of the Clearfield, Utah plant in December 2013.

Production Dates : DEC 16, 2013 - DEC 16, 2013

VIN (Vehicle Identification Number) Range

Begin : 1UYVS2537FU052601

End : 1UYVS2538FU052610

 Not sequential VINs**Description of Defect :**

Description of the Defect : Meritor reported approximately 30% of the bolts that mount the EX225L and Bendix disc brake caliper to the mounting flange on certain MPA suspensions did not meet the specified torque requirements causing the bolts to be loose.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Bolts that mount the EX225L and Disc brake caliper to the mounting flange are coming loose due to improper torque.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Meritor, Inc.

Address : NR

NR

Country : NR

Chronology :

Received Safety Recall from Meritor NHTSA File 15E083 on 11/17/2015 which prompted Utility Trailer Manufacturing to file.

Description of Remedy :

Description of Remedy Program : Trailers that potentially contain the suspect EX225L and Bendix Calipers with loose bolts will be removed from service and inspected using the Meritor TP-15141 to ensure the caliper bolts are properly torqued. Part and labor cost will be reimbursed through standard warranty. Meritor will reimburse at the OEM SRT for checking the caliper bolts and replacement if necessary.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : Only 10 units were purchased with EX225L and Bendix disc brake caliper. These 10 units have already been in service for 23 months without issue.

Recall Schedule :

Description of Recall Schedule : Selling dealer and customer were notified on 11/04/2015

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported