

Part 573 Safety Recall Report**15V-785****Manufacturer Name :** Supreme Corporation**Submission Date :** NOV 20,2015**NHTSA Recall No. :** 15V-785**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Supreme Corporation

Address : 2581 East Kercher Road
Goshen IN 46528

Company phone : 999

Population :

Number of potentially involved : 30

Estimated percentage with defect : 95

Vehicle Information :

Vehicle : 2014-2015 Supreme Classic American Trolley

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Trolley Windshield

Production Dates : OCT 01, 2014 - NOV 02, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Noncompliance :**

Description of the Noncompliance : Due to a supplier error, these vehicles may be equipped with windshields that meet with AS2 or AS3 specification, rather than the AS1 specification required by FMVSS No. 205, Glazing materials.

FMVSS 1 : 205 - Glazing materials

FMVSS 2 : NR

Description of the Safety Risk : AS grades specify transmissivity for designated position on vehicle reduction in transmissivity could affect driver visibility under certain conditions

Description of the Cause : Supplier shipped the incorrect product, which was subsequently installed in the subject vehicles.

Identification of Any Warning that can Occur : N/A

Supplier Identification :**Component Manufacturer**

Name : Thompson IG, LLC

Address : 3196 Thompson Road
Fenton MICHIGAN 48430

Country : United States

Chronology :

On October 30, 2015, Supreme was contacted by a distributor with questions concerning the windshield marking on a Classic American trolley in the distributor's inventory. The distributor sent photographs of the windshield marking to Supreme, and Supreme initiated an investigation into the windshield type and markings, including discussions with the glass supplier. This investigation revealed that the supplier may have shipped AS2 and/or AS3 glass, which was subsequently installed on the subject vehicles. On November 5, 2015, based upon this investigation, Supreme determined that the subject vehicles may not comply with FMVSS No. 205, Glazing.

Description of Remedy :

Description of Remedy Program : Supreme will replace the noncompliant windshield with AS1 product in compliance with FMVSS No. 205.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NOV 23, 2015 - NOV 27, 2015

Planned Owner Notification Date : DEC 21, 2015 - DEC 24, 2015

* NR - Not Reported