

**Part 573 Safety Recall Report****15V-791****Manufacturer Name :** Wabash National Corporation**Submission Date :** NOV 20,2015**NHTSA Recall No. :** 15V-791**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Wabash National Corporation

Address : PO Box 6129

1000 Sagamore Parkway South Lafayette IN 47903

Company phone : 999

**Population :**

Number of potentially involved : 91

Estimated percentage with defect : 30

**Vehicle Information :**

Vehicle : 2013-2015 Wabash National Van trailers

Vehicle Type : TRAILERS

Body Style : UNKNOWN

Power Train : NR

**Descriptive Information :** This Recall impacts Wabash Trailer products equipped with certain Meritor MPA suspensions that are equipped with either EX225L2/ EX225L+/ or Bendix ADB22X disc brakes.

Production Dates : DEC 09, 2013 - AUG 25, 2015

**VIN (Vehicle Identification Number) Range**

Begin : 1JJV532B3GL953857

End : 1jjV532B0G1954044

 Not sequential VINs**Description of Defect :**

Description of the Defect : On the EX225L2/ EX225L+/ or Bendix ADB22X disc brakes, some of the caliper bolts were not torqued to specification.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If all of the caliper bolts were not torqued to specification, they could back out causing the caliper to detach from the axle flange. This could affect braking performance and cause the braking system to default to spring control.

Description of the Cause : N/A

Identification of Any Warning that can Occur : N/A

**Supplier Identification :****Component Manufacturer**

Name : Meritor Inc

Address : 2135 West Maple Road  
Troy MICHIGAN 48084

Country : United States

**Chronology :**

8/21/15 Prime notified Wabash and Meritor that a trailer with an MPA40S165WP suspension equipped with EX225L disk brakes had the brake in the RS rear position fall off of the axle due to the loss of all the caliper bolts

8/25/15 to 8/28/15 Meritor sent a team to Wabash to inspect 109 trailers built for Prime. 33 suspension had at least 1 under torqued caliper bolt

9/10/15 Customer list was completed

9/18/15 Vin numbers identified

**Description of Remedy :**

Description of Remedy Program : Caliper bolts under torqued. Remedy is inspection of caliper bolt torque to ensure they meet specification. Reimbursement of pre-notification remedies and reimbursement instructions will be included in the Owners Notification.

How Remedy Component Differs from Recalled Component : N/A

Identify How/When Recall Condition was Corrected in Production : August 31, 2015 DC nut runner was installed, eliminated the manual process for torquing the caliper bolts.

**Recall Schedule :**

Description of Recall Schedule : Recall schedule is dependent upon receiving final approval from NHTSA. Dates supplied are preliminary estimates only and we anticipate an earlier date for notifications..

Planned Dealer Notification Date : JAN 15, 2016 - JAN 15, 2016

Planned Owner Notification Date : JAN 15, 2016 - JAN 15, 2016

\* NR - Not Reported