

Part 573 Safety Recall Report

15V-797

Manufacturer Name : Newmar Corporation

Submission Date : MAY 06, 2016

NHTSA Recall No. : 15V-797

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Population :

Number of potentially involved : 10

Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : 2016-2016 Newmar King Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, manufactured by Newmar Corporation, a window having egress glass may not have been installed at the driver's side dinette table window. Not having an egress window on the opposite side of the entry door is a critical safety issue. An egress window is required per code for a second way to escape the vehicle if an accident/crash occurs. Correction: Newmar Dealers will inspect the window at the dinette table and add an egress window if needed.

Production Dates : MAR 09, 2015 - SEP 14, 2015

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, manufactured by Newmar Corporation, a window having egress glass may not have been installed at the driver's side dinette table window. Not having an egress window on the opposite side of the entry door is a critical safety issue.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Not having an egress window on the opposite side of the entry door is a critical safety issue. An egress window is required per code for a second way to escape the vehicle if an accident/crash occurs.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

10/29/2015; Newmar Corporation was made aware of a potential equipment defect relating to motor vehicle safety that may exist in specific 2016 Newmar King Aire motorhomes identified as potentially defective by Newmar.

11/09/2015 Newmar sent Notice of Defect to NHTSA

Description of Remedy :

Description of Remedy Program : Newmar Dealers will inspect the window at the dinette table and add an egress window if needed.

How Remedy Component Differs from Recalled Component : Not having egress glass in the window.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : JAN 08, 2016 - NR

Planned Owner Notification Date : JAN 08, 2016 - NR

* NR - Not Reported