

Part 573 Safety Recall Report**15V-831**

Manufacturer Name : Forest River, Inc.
Submission Date : DEC 09, 2015
NHTSA Recall No. : 15V-831
Manufacturer Recall No. : 51-12072015-0119

**Manufacturer Information :**

Manufacturer Name : Forest River, Inc.
 Address : 55470 CR 1
 P.O. Box 3030 Elkhart IN 46515-3030
 Company phone : 219-533-5934

Population :

Number of potentially involved : 721
 Estimated percentage with defect : 75

Vehicle Information :

Vehicle : 2016-2016 Forest River, Inc. Evo - CSJT1860, CSJT2050, CSJT2250, CSJT2300, CSJT2360, CSJT2460, CSJT2550, CSJT2700, CSJT2850, CSJT3250

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Evo is a recreational vehicle manufactured by Forest River, Inc.

Production Dates : SEP 21, 2015 - DEC 04, 2015

VIN (Vehicle Identification Number) Range

Begin : 4X4TSJE23GC015070 End : 4X4TSJY23GC015419 Not sequential VINs

Vehicle : 2016-2016 Forest River, Inc. Salem - CSMT21RBS, CSMT26TBUD, CSMT27RKSS, CSMT27RLSS, CSMT27TDSS, CSMT30QBSS, CSMT32BHDS

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Salem is a recreational vehicle manufactured by Forest River, Inc.

Production Dates : SEP 17, 2015 - DEC 01, 2015

VIN (Vehicle Identification Number) Range

Begin : 4X4TSMF21GC013799 End : 4X4TSMH23GC013901 Not sequential VINs

Vehicle : 2016-2016 Forest River, Inc. Sandstorm - CSCF285GSLR, CSCF335GSLR, CSCT180GSLC, CSCT180SLC, CSCT210SLC, CSCT240GSLC, CSCT240SLC, CSCT250GSLC, CSCT250SLC, CSCT270GSLR, CSCT270SLR, CSCT273GSLR, CSCT281GSLR

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Sandstorm is a recreational vehicle manufactured by Forest River, Inc.

Production Dates : SEP 18, 2015 - DEC 03, 2015

VIN (Vehicle Identification Number) Range

Begin : 4X4TSCC25GC007728

End : 4X4TSCT29GC007893

Not sequential VINs

Vehicle : 2016-2016 Forest River, Inc. Shockwave - CSHF28SAGDX, CSHF33SAGDX, CSHT18SSMX, CSHT21FQMX, CSHT24FQGMX, CSHT24FQMX, CSHT25FQGMX, CSHT25FQMX, CSHT27FQDX, CSHT27FQGDY, CSHT27SAGDX, CSHT28FQGDY, CSHT28RCGDY

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Shockwave is a recreational vehicle manufactured by Forest River, Inc.

Production Dates : SEP 21, 2015 - DEC 03, 2015

VIN (Vehicle Identification Number) Range

Begin : 4X4TSHC27GC002995

End : 4X4TSHT20GC003079

Not sequential VINs

Vehicle : 2016-2016 Forest River, Inc. Stealth - CSFFWA2812G, CSFFWA3316G, CSFTRG2810G, CSFTSA2515, CSFTSS1913, CSFTSS2116, CSFTWA2313, CSFTWA2313G, CSFTWA2715, CSFTWA2715G, CSFTWA2817, CSFTWA2817G, CSFTWA2916, CSFTWA2916G

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Stealth is a recreational vehicle manufactured by Forest River, Inc.

Production Dates : SEP 15, 2015 - DEC 02, 2015

VIN (Vehicle Identification Number) Range

Begin : 4X4TSFC25GC015085

End : 4X4TSFU29GC015430

Not sequential VINs

Vehicle : 2016-2016 Forest River, Inc. Wildwood - CWDT21RBS, CWDT26TBSS, CWDT27RKSS, CWDT27RLSS, CWDT27TDSS, CWDT30QBSS, CWDT32BHDS

Vehicle Type : TRAILERS

Body Style :

Power Train : NR

Descriptive Information : Wildwood is a recreational vehicle manufactured by Forest River, Inc.

Production Dates : SEP 18, 2015 - NOV 30, 2015

VIN (Vehicle Identification Number) Range

Begin : 4X4TWDF28GC044827

End : 4X4TWDW22GC044919

Not sequential VINs

Description of Defect :

Description of the Defect : The subject vehicles were manufactured with the wrong liquid propane (L.P.)

detector and carbon monoxide detector. The installed component only includes a liquid propane detector and not a carbon monoxide detector.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Any recreational vehicle missing a carbon monoxide detector will not alert the occupants to an elevated level of carbon monoxide. The presence of an elevated level of carbon monoxide may lead to serious injury or death.

Description of the Cause : The subject L.P. detector/carbon monoxide detector combination was incorrectly ordered from a partner supplier of Forest River and installed in the subject vehicles. The subject component was misidentified by Forest River's purchasing department based on an incorrect part number.

Identification of Any Warning that can Occur : None.

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Forest River – Office of Corporate Compliance was made aware of this defect on December 4, 2015 by the manufacturing facilities manager. The manufacturing plant had a customer's vehicle in for an unrelated service and upon inspection it was discovered that the vehicle did not have a carbon monoxide detector integrated with the L.P. detector. Upon further inspection of the vehicle, it was determined that the vehicle in fact did not have a carbon monoxide alarm.

Forest River's Corporate Recall Committee convened on December 7, 2015 and decided to recall all the subject vehicles that were identified in the scope of the purchase orders with the incorrect part numbers.

Description of Remedy :

Description of Remedy Program : Forest River will provide the correct combination L.P. detector/carbon monoxide detector free of charge to the customer and dealerships.

How Remedy Component Differs from Recalled Component : The correct L.P. detector/carbon monoxide detector that will replace the currently installed L.P. detector. The difference will be visible inscribing on the component and owner maintenance instructions will reference the L.P. detector with a carbon monoxide detector.

Identify How/When Recall Condition was Corrected in Production : Several steps have been implemented at the manufacturing facility to ensure the correct alarm is used for installation in the vehicle. A multi-point inspection process

will be used prior to the component being installed in the vehicles, including a visual inspection by the component receiver(s), quality control group and electrician who installs the component. At the conclusion of each visual inspection, the parties will sign a report that is given to the production manager daily that verifies that the component that was installed is an L.P. detector/carbon monoxide detector. Lastly, the purchasing department removed the incorrect part number from the purchase order and now only has one part number to select from when ordering an L.P. detector/carbon monoxide detector.

Recall Schedule :

Description of Recall Schedule : Forest River has the utmost urgency in our recalls. Forest River has sent suspected VIN numbers to our third party vendor that is licensed to pull data on the current owner of the vehicles. Forest River intends on pushing the mailing out as soon as NHTSA provides any correction(s) and an Acknowledgement Letter.

Planned Dealer Notification Date : FEB 02, 2016 - FEB 02, 2016

Planned Owner Notification Date : FEB 02, 2016 - FEB 02, 2016

* NR - Not Reported