

Part 573 Safety Recall Report**15V-835****Manufacturer Name :** Trail Boss Conversions, Inc.**Submission Date :** FEB 15, 2016**NHTSA Recall No. :** 15V-835**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Trail Boss Conversions, Inc.

Address : 308 W US HWY 40

BATES CITY MO 64011

Company phone : 816-690-7133

Population :

Number of potentially involved : 1

Estimated percentage with defect : 0

Vehicle Alterer Information :

Vehicle : 2013-2013 Bloomer Horse Trailer

Descriptive Information : We put the living quarters conversion in 1 Bloomer horse trailer that had a recall on the Atwood On Demand Water Heater that was installed in this unit.

Production Dates : OCT 01, 2013 - NOV 29, 2013

Description of Defect :

Description of the Defect : Atwood has found that the water flow adjustment feature on their models OD50, OD50CW and OD45 On Demand Water Heater poppet valve may have drifted during transit or may have been set at the factory such that the water flow is at .3 gal/min or less. If this adjustment setting is allowed to drift to, or has been set at, .3 gal/min or less, the condition of concern can occur and can lead to a scald injury to the user.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the On Demand Water Heater poppet valve drifted during transit or was set at the factory so that the water flow is at .3 gal/min or less, a scald injury can occur.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Atwood Mobile Products

Address : 1120 N Main Street

Elkhart INDIANA 46514

Country : United States

Chronology :

Atwood advised Trail Boss Conversions, Inc. of its defect determination via email dated 11/5/15. Trail Boss Conversions, Inc. is not aware of any scald injuries in its vehicle that appear to be related to this defect.

Description of Remedy :

Description of Remedy Program : Atwood has arranged to conduct a recall to remedy the potential defect in the Trail Boss Conversions, Inc. vehicle at no charge to the vehicle owner. See Recall 15E-087. Pursuant to 49CFR 573.6(c)(8)(I) and 573.13, owner will be advised that Atwood will reimburse them if they have incurred costs to obtain a remedy for an ODWH containing such a defect prior to their receipt of the notification.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : FEB 11, 2016 - FEB 16, 2016

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported