

Part 573 Safety Recall Report**15V-847****Manufacturer Name :** Vanguard National Trailer Corporation**Submission Date :** DEC 15, 2015**NHTSA Recall No. :** 15V-847**Manufacturer Recall No. :** 15E083**Manufacturer Information :**

Manufacturer Name : Vanguard National Trailer Corporation

Address : 289 E. Water Tower Drive

Monon IN 47959

Company phone : 999

Population :

Number of potentially involved : 85

Estimated percentage with defect : 30

Vehicle Information :

Vehicle : 2015-2016 Vanguard CIMC Dry vans and refrigerated trailers

Vehicle Type : TRAILERS

Body Style : VAN

Power Train : NR

Descriptive Information : Meritor MPA suspensions with EX225L and Bendix disc brake caliper bolts may not be to torque specification allowing some bolts to come loose.

Production Dates : OCT 22, 2014 - OCT 02, 2015

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : Bolts on the brake caliper to the mounting flange potentially not to torque specification.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : May cause the bolts to loosen and caliper to disengage from the rotor.

Description of the Cause : Mounting bolts not to torque specification

Identification of Any Warning that can Occur : Brakes may not function properly or caliper come loose and become wedged in disc wheel.

Supplier Identification :**Component Manufacturer**

Name : Meritor Inc.

Address : 2135 West Maple Road
Troy MICHIGAN 48084

Country : United States

Chronology :

Meritor suspensions were assembled between December 1, 2013 and September 1, 2015 in Frankfort Kentucky and shipped to Vanguard National Trailer in the same time frames. On November 25, 2105 Vanguard CIMC was notified of safety recall 15E083.

Description of Remedy :

Description of Remedy Program : Suspect vehicles will need inspected for loose bolts and taken out of service. If the inspection finds bolts missing new ones are to be installed and properly torqued per the Meritor TP-15141 service bulletin. Defective parts must be returned by contacting the Meritor customer service OnTrac Customer service group. Parts will be furnished by Meritor and reimbursement for inspections and repairs will be done through the normal Meritor warranty program.

How Remedy Component Differs from Recalled Component : Bolts will be set to proper torque specification.
Identify How/When Recall Condition was Corrected in Production : I do not have that information available from the supplier.

Recall Schedule :

Description of Recall Schedule : Vanguard CIMC will notify our dealers and customer by mail along with the inspection, repair and reimbursement instructions from Meritor.

Planned Dealer Notification Date : DEC 23, 2015 - DEC 30, 2015

Planned Owner Notification Date : DEC 23, 2015 - DEC 30, 2015

* NR - Not Reported