

Part 573 Safety Recall Report**15V-850****Manufacturer Name :** Mitsubishi Fuso Truck of America, Inc.**Submission Date :** DEC 17, 2015**NHTSA Recall No. :** 15V-850**Manufacturer Recall No. :** C1008210**Manufacturer Information :**

Manufacturer Name : Mitsubishi Fuso Truck of America, Inc.

Address : 2015 Center Square Road

Logan Township NJ 08085

Company phone : 999-999-9999

Population :

Number of potentially involved : 9,456

Estimated percentage with defect : 100

Vehicle Information :

Vehicle : 2012-2015 Mitsubishi Fuso FEC52, FEC72, FEC92, FGB72

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : Cab over engine

Production Dates : APR 08, 2011 - JUL 22, 2014

VIN (Vehicle Identification Number) Range

Begin : NR

End : NR

 Not sequential VINs**Description of Defect :**

Description of the Defect : On certain affected vehicles, the fuel return hose is comprised of a material that deteriorates when subjected to various chemicals and lubricants, such as those used when cleaning the vehicle or used in certain rear body applications.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Normal vehicle operation and maintenance may cause the fuel return hose to swell and come off, resulting in a fuel leak. In the worst case, the fuel could ignite, resulting in an engine fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR

Address : NR

NR

Country : NR

Chronology :

On December 11, 2015, MFTBC notified MFTA that MFTBC had decided to conduct a Safety Recall Campaign in the U.S. and Canadian markets.

After deliberate study of failed parts, MFTBC determined that the failure is caused by improper material composition. Normal vehicle operation and maintenance may cause the fuel return hose to swell and come off, resulting in a fuel leak. In the worst case, the fuel could ignite, resulting in an engine fire. MFTA received ninety-one (91) Warranty Service Claims (WSCs) and zero (0) Product Quality Reports (PQRs) relating to affected vehicles. MFTA has received no notice of accident or injury relating to the subject component.

Description of Remedy :

Description of Remedy Program : The fuel return hose will be inspected. If a defective hose is in place, it will be replaced with an improved hose.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : A schedule for dealer and owner notification has yet to be determined. MFTA will provide this information as soon as possible.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported