

Part 573 Safety Recall Report**15V-890****Manufacturer Name :** Compass Conversions, LLC**Submission Date :** DEC 30, 2015**NHTSA Recall No. :** 15V-890**Manufacturer Recall No. :** 15E-087**Manufacturer Information :**

Manufacturer Name : Compass Conversions, LLC

Address : 1822 Industrial Blvd

Temple TX 76504

Company phone : 99999

Population :

Number of potentially involved : 3

Estimated percentage with defect : 1

Vehicle Alterer Information :

Vehicle : 2014-2014 Bloomer Trailers Horse Trailer 1B9BG3516FS511332

Descriptive Information : Possible Defect Atwood OD50 water heater

Production Dates : JUL 24, 2014 - JUL 24, 2014

Vehicle : 2015-2015 Platinum Trailer Horse Trailer 5HMXG3938F1007698

Descriptive Information : Possible defective Atwood OD50 water heater

Production Dates : MAY 18, 2015 - MAY 18, 2015

Vehicle : 2015-2015 Stock Stock

Descriptive Information : Item in our stock

Production Dates : NOV 06, 2015 - NOV 06, 2015

Description of Defect :

Description of the Defect : Atwood has found that the water flow adjustment feature on their models OD50, OD50CW, and OD45 the On Demand Water Heater poppet valve may have drifted during transit or may have been set at the factory such that the water flow is at .3gal/minute or less, the condition of concern can occur and can lead to a scald injury to the user.

FMVSS 1 :NR

FMVSS 2 :NR

Description of the Safety Risk : Potential for scald injury

Description of the Cause : Atwood has found that the water flow adjustment feature on their models OD50, OD50CW, and OD45 the On Demand Water Heater poppet valve may have drifted during transit or may have been set at the factory such that the water flow is at .3gal/minute or less, the condition of concern can occur and can lead to a scald injury to the user.

Identification of Any Warning that can Occur : Atwood has found that the water flow adjustment feature on

their models OD50, OD50CW, and OD45 the On Demand Water Heater poppet valve may have drifted during transit or may have been set at the factory such that the water flow is at .3gal/minute or less, the condition of concern can occur and can lead to a scald injury to the user.

Supplier Identification :**Component Manufacturer**

Name : Atwood

Address : 1120 N Main Street

Elkhart INDIANA 46514

Country : United States

Chronology :

5. Chronological Summary of events leading to the is determination:

Atwood advised Compass Conversions of its defect determination via email dated 11/5/2015. Compass Conversions is not aware of any scald injuries in its vehicles that appear to be related to this defect.

Description of Remedy :

Description of Remedy Program : Atwood has arranged to conduct a recall to remedy the potential defect in Compass Conversion's vehicles at no charge to the vehicle owners. See Recall 15E-087. Pursuant to 49CFR573.6(c)(8)(i) and 573.13, owners will be advised that Atwood will reimburse them if they have incurred costs to obtain a remedy for an ODWH containing such a defect prior to their receipt of the notification.

How Remedy Component Differs from Recalled Component : In process from Atwood

Identify How/When Recall Condition was Corrected in Production : In process from Atwood

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

Purchaser Information :

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :

Address :

Country :

Company Phone :

* NR - Not Reported