

GM CUSTOMER CARE AND AFTERSALES
DCS3643
URGENT - DISTRIBUTE IMMEDIATELY

Date: April 29, 2015

Subject: 15176C – Service Update Bulletin
Sunroof Switch Compliance
Service Procedure Revised

Models: 2013-2015 Chevrolet Malibu
Equipped with Power-Operated Roof Panel System (RPO CF5)

To: All Chevrolet Dealers

Attention
: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
Used Vehicle Sales Manager, and Warranty Administrator

The service procedure has been revised to clarify sunroof window operation. Please see the attached bulletin for details and discard all copies of bulletin 15176B.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES