

GM CUSTOMER CARE AND AFTERSALES  
DCS3620  
URGENT - DISTRIBUTE IMMEDIATELY

Date: April 8, 2015

Subject: 15176B – Noncompliance Recall  
Sunroof Switch Compliance  
Customer Letter Added

Models: 2013-2015 Chevrolet Malibu Equipped with Power-Operated  
Roof Panel Systems (CF5)

To: All Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and  
Service Director, Parts Manager, New Vehicle Sales Manager,  
Used Vehicle Sales Manager, and Warranty Administrator

Bulletin 15176B has been revised to include a copy of the customer letter. Please discard all copies of bulletin 15176A.

**Customer Letter Mailing**

The customer letter mailing will begin on April 21, 2015.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES