

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS4180
URGENT - DISTRIBUTE IMMEDIATELY

Date: September 01, 2016

Subject: 14574D – Safety Recall
Engine Oil Leak on Exhaust Manifold
Revised Warranty Transaction and Service Procedure sections

Models: 2004 Buick Regal
2004 Chevrolet Impala
2004 Chevrolet Monte Carlo
2004 Pontiac Grand Prix
Equipped with a 3.8L V6 engine (RPO L26, L32, L36 or L67)

To: All General Motors Dealers

This bulletin is being revised to enhance the Service Procedure with additional information to assure proper sealing of the replacement valve cover gasket, and to revise the Warranty Transaction Information section. Please discard all copies of bulletin 14574C.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS