

# Federal Recall Information

---

**415-E**

## Supplier

Peterbilt

---

## Description

Model 220 Cruise Control

---

## Release Date

04/10/2015

---

## Introduction

Peterbilt has determined that on certain 2015 and 2016 Model 220 trucks pressing the Cruise Control SET Decrease speed button (-) on the steering wheel will increase rather than decrease the vehicle's speed when depressed ( a momentary press increase speed by 1 mph, pressing and holding will constantly increase speed until the button is released).

An unexpected increase in vehicle speed may increase the risk of a crash.

---

## Resolution

Reflash the engine software to resolve the issue.

---

**It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.**

---

## Warranty

The SIR system will indicate chassis involved in this field repair with the designator for "**415-E**". If the vehicle is affected and is shown to have an open campaign, please complete the work and file a quick claim "**415-E**".

---

## **Parts**

There are no parts for this recall.

---

## **Labor**

Peterbilt will reimburse the dealer for 0.8 hours labor for reflashing the engine to update the software.

---

## **Procedure**

[415-E Euro 6 Cruise Control Programming Procedure](#)

---

## **Attachments**

[415-E Chassis List](#)