



**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

Safety Recall: US: 15V-207
CAN: 2015-255
Safety Advisory: 15-230
June 29, 2015

SAFETY ADVISORY 15-230

«Owner_name»
ATTN: Service Manager
«Street»
«City», «State» «Zip»
«Country»

Dear «Owner_name»,

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model Dutchmen 2015-2016 Aspen Trail, Coleman, Denali, Razorback, Rubicon, and Voltage and Keystone 2015 Bullet, 2015-2016 Cougar, 2015-2016 Hideout, 2016 Passport, 2015-2016 Sprinter, and 2015-2016 Springdale Fifth Wheels and Travel Trailers. As a result, Keystone RV is conducting a safety recall.

Reason for this recall

It has been decided the vehicles identified in this recall population equipped with axles manufactured by Lippert Components Inc. (LCI) and Tru Ryde or Axle Tek 10" or 12" wheel hubs may have been manufactured with wheel studs which could break. If more than one wheel stud breaks and the vehicle is in motion, it could result in the separation of the wheel from the vehicle leading to an increased risk of property damage and/or vehicle crash. The vehicles included in the recall are:

2015 Aspen Trail FH922580 – FH922659
2016 Aspen Trail GH920040 – GH920173
2015 Coleman FH933464 – FH933488
2016 Coleman GH930210 – GH930224
2016 Denali GP940000 – GP940084
2016 Razorback GH980000 – GH980005
2016 Rubicon GH985000 – GH985054
2016 Voltage GZ990000 – GZ990091
2015 Cougar F2509503 – F2509941
2016 Cougar G2500152 – G2500699
2015 Hideout FN207727 – FN207828
2016 Passport GX410088 – GX410176
2016 Sprinter G1530000 – G1530206
2016 Springdale GG100000 – GG100106

2015 Aspen Trail FY922586 – FY922645
2016 Aspen Trail GY920000 – GY920015
2015 Coleman FY933354 – FY933389
2015 Denali FP940887 – FP940973
2015 Razorback FH980073 – FH980081
2015 Rubicon FH985364 – FH985426
2015 Voltage FZ991414 – FZ991497
2015 Bullet FX425882 – FX426009
2015 Cougar FC509590 – FC509856
2016 Cougar GC500000 – GC500497
2016 Hideout GN200000 – GN200089
2015 Sprinter F1533056 – F1533227
2015 Springdale FG105075 – FG105283

Our records indicate unit(s) sold or in your present lot inventory fall within this range, which will require immediate preventative action.

Important: If some of the units are still in your inventory, Federal Law requires you to complete the recall service on those units before retail delivery. The unit VIN(s) our records indicate are presently in your inventory or have been sold are as follows:

«VIN1»	«VIN2»	«VIN3»	«VIN4»	«VIN5»
«VIN6»	«VIN7»	«VIN8»	«VIN9»	«VIN10»
«VIN11»	«VIN12»	«VIN13»	«VIN14»	«VIN15»
«VIN16»	«VIN17»	«VIN18»	«VIN19»	«VIN20»
«VIN21»	«VIN22»	«VIN23»	«VIN24»	«VIN25»
«VIN26»	«VIN27»	«VIN28»	«VIN29»	«VIN30»
«VIN31»	«VIN32»			

Asterisk = *retail-sold unit

Claims for the units which have been serviced must be submitted. Claims submitted will be used by Keystone to record recall service completions and provide dealer payments. Attached is a copy of the Safety Advisory #15-230, which details how to remedy the situation and the proper reimbursement procedures.

We apologize for any inconvenience this situation may cause and greatly appreciate your cooperation. Should you have any questions or concerns regarding this correspondence or the attached Safety Advisory, please feel free to contact us.

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
Sales & Service Manager

cc. National Highway Traffic Safety Administration (NHTSA)
cc. Transport Canada

PO Box 2000 – Goshen, IN 46527-2000
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com