

Federal Recall Information

15KWE

Supplier

Kenworth

Description

Delco-Remy 40SI alternator cable rubs A/C Line

Release Date

6/25/2015

Introduction

Kenworth Truck Company has decided that a defect which relates to motor vehicle safety exists in certain model year 2014 - 2016 Kenworth T660, T680, and T880, trucks manufactured February 18, 2013 to April 8, 2015. A total of 585 chassis (533 U.S. and 52 Canada) are involved in this recall.

Situation

The affected trucks, equipped with PACCAR MX-13 engines and Delco-Remy 40SI alternators, have alternator charge cables that may chafe against a formed metal refrigerant discharge line.

If the alternator cable rubs through its insulation, an electrical short may occur, increasing the risk of a fire.

Resolution

Kenworth is working with the component supplier to develop a permanent fix for this issue.

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Parts

Early Notification: Parts are not currently available. A second notification will be made when parts are available.

Attachments

 [Dealer\Chassis List](#)

 [Customer Letter](#)

Authored by: JS