



**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

Safety Recall: US: 15V-317
CAN: 2015-275
Safety Advisory: 15-225
June 18, 2015

SAFETY ADVISORY 15-225

«Owner_name»
ATTN: Service Manager
«Street»
«City», «State» «Zip»
«Country»

Dear «Owner_name»,

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model Dutchmen 2015 Aerolite, Denali, Kodiak, and Voltage Fifth Wheels and Travel Trailers and Keystone 2015 Alpine, Avalanche, Bullet, Carbon, Cougar, Fuzion, Impact, Laredo, Montana, Montana High Country, Outback, Passport, Raptor and Sprinter Fifth Wheels and Travel Trailers. As a result, Keystone RV is conducting a safety recall.

Reason for this recall

It has been decided that the self-tapping screws attaching the Norco slide room cable bracket to the drive chain may fail. If all four (4) screws for the cable brackets holding the room in the closed position fail, the slide room will not be secured to the sidewall during travel and the slide room may extend increasing the risk of vehicle crash. The vehicles included in the recall are:

2015 Aerolite	FP910811 - FP910838	2015 Denali	FP940836 - FP940878
2015 Kodiak	FJ972055 - FJ972078	2015 Voltage	FZ991339- FZ991412
2015 Alpine	FE780866 - FE780892	2015 Avalanche	FE760629 - FE760656
2015 Bullet	FD425761 - FD426136	2015 Carbon	FR805862 - FR805894
2015 Cougar	F2509049 - F2509205	2015 Cougar X-Lite	FV509290 - FV509560
2015 Fuzion	FF811096 - FF811151	2015 Impact	FF815708 - FF815712
2015 Laredo	FK602376 - FK602466	2015 Montana	F4702338 - F4702490
2015 Montana High Country	FA740848 - FA740903	2015 Outback	FB453808 - FB453990
2015 Passport	FT415676- FT415683	2015 Raptor	FR800990- FR801027
2015 Sprinter	F1532915- F1533061		

Our records indicate unit(s) sold or in your present lot inventory fall within this range, which will require immediate preventative action.

Important: If some of the units are still in your inventory, Federal Law requires you to complete the recall service on those units before retail delivery. The unit VIN(s) our records indicate are presently in your inventory or have been sold are as follows:

«VIN1»	«VIN2»	«VIN3»	«VIN4»	«VIN5»
«VIN6»	«VIN7»	«VIN8»	«VIN9»	«VIN10»
«VIN11»	«VIN12»	«VIN13»	«VIN14»	«VIN15»
«VIN16»	«VIN17»	«VIN18»	«VIN19»	«VIN20»
«VIN21»	«VIN22»	«VIN23»	«VIN24»	«VIN25»
«VIN26»				

Asterisk = *retail-sold unit

Claims for the units which have been serviced must be submitted. Claims submitted will be used by Keystone to record recall service completions and provide dealer payments. Attached is a copy of the Safety Advisory #15-225, which details how to remedy the situation and the proper reimbursement procedures.

We apologize for any inconvenience this situation may cause and greatly appreciate your cooperation. Should you have any questions or concerns regarding this correspondence or the attached Safety Advisory, please feel free to contact us.

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
Sales & Service Manager

cc. National Highway Traffic Safety Administration (NHTSA)
cc. Transport Canada