



419 W. Pike St., Jackson Center, OH 45334

## **IMPORTANT SAFETY RECALL**

**Airstream Interstate Vans**

**NHTSA Recall Number 15V336**

**Transport Canada Recall Number 2015-218**

**DATE:** 6/3/2015

**TO:** Airstream Dealer

**PROBLEM:**

On Airstream Interstate Vans, when the optional side screen door is in the closed position and the vehicle's curbside sliding door closed, the screen door may become inoperable. In the event of a need for emergency escape from the vehicles, occupants may not be able to use this exit for egress, increasing the chance for personal injury.

**RANGE OF VEHICLES INVOLVED:**

2015 and 2016 model year vans with the optional side screen door.

**WARRANTY REIMBURSEMENT:**

A notice of this recall has been sent to affected retail owners. A copy of the Owner's letter is included for your review. They may request that you complete the repair. If so, please follow the warranty reimbursement procedure. If the unit and/or units are in your inventory, or if you are requested to perform the repair for the retail customer, please complete the advised repair and send in a warranty claim referencing this recall number for reimbursement. The time allowed for repair is 30 minutes.

**SERVICE ACTION:**

The repair is to attach a block/stop on the vehicle's sliding door which keeps the sliding door from shutting if the screen door is closed. See attached repair procedure.

Enclosure - Owner's Letter

Rick March  
General Manager of Airstream Customer Service Group

Re: NHTSA Recall No. 15-V  
Transport Canada Recall No. 2015-218